

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22002674/ENCE2

Date: 10/08/2022

REFERENCE

Insured/Claimant:	WONG CHUI FONG	Policy No:	1900012908-02		
Date of Loss:	20/03/2022	Nature of Claim:	OD	Claim No:	9168862547SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW1333G		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK072925
Reg. Date:	30/01/2019 (Man. Year: 2018)	Chassis No:	WAUZZZF50KA008792
Colour:	Black	Odometer:	30922 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$155,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	42,499.70	16,315.92	26,183.78	61.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,224.00	9,624.00	4,600.00	32.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	56,723.70	25,939.92	30,783.78	54.27
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	55,123.70	24,339.92	30,783.78	55.84
+ GST 7.00/7.00% (S\$)	3,858.66	1,703.79	2,154.87	55.85
Nett Amount (S\$)	58,982.36	26,043.71	32,938.65	55.84

INSPECTION

Date of Assignment:	23/03/2022		
Date Inspected:	23/03/2022	Inspected At:	24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	10.0 days		

Adjuster: CHEN TSUE YEE

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,492.70 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	425.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	Broken	254.00 FS	*203.20 FS
4	1		*FRONT CENTRE SPOILER	Cut	599.00 FS	*478.80 FS
5	2		*FRONT WHEEL SPOILER UPPER	Broken	164.00 FS	*130.24 FS
6	1		*FRONT WHEEL SPOILER LOWER LH	Missing	39.00 FS	*31.12 FS
7	1		*FRONT WHEEL SPOILER LOWER RH	Not Necessary	40.00 FS	*- FS
8	1		*NOISE INSULATION FRONT	Broken	640.00 FS	*512.00 FS
9	1		*NOISE INSULATION REAR	Broken	437.00 FS	*349.60 FS
10	1		*UNDERBODY TRIM FRONT LH	Broken	51.00 FS	*40.80 FS
11	1		*UNDERBODY TRIM LH	Broken	376.00 FS	*300.40 FS
12	2		*UNDERRUN BAR LH / RH	Not Necessary	46.00 FS	*- FS
13	1		*ALUMINIUM RIM	Cut	1,889.00 FS	*1,511.20 FS
14	1		*FRONT WHEEL HOUSING LINERS LH / RH	N/S Torn	598.00 FS	*238.80 FS
15	1		*FRONT WHEEL HOUSING LINERS ATTACHMENT PARTS	Not Necessary	176.00 FS	*- FS
16	1		*LOCK CARRIER	Broken	1,127.00 FS	*901.60 FS
17	2		*RADIATOR SUPPORT	Not Necessary	85.00 FS	*- FS
18	6		*COOLANT PREMIX 1.0L	Necessary	282.00 FS	*225.60 FS
19	1		*SUBFRAME	Not Necessary	2,096.00 FS	*- FS
20	1		*FRONT WISHBONE LINK	Bent	605.00 FS	*483.60 FS
21	1		*SUSPENSION GUIDE LOWER FRONT LH	Not Necessary	1,057.00 FS	*- FS
22	2		*SUSPENSION GUIDE UPPER FRONT / REAR LH	Not Necessary	1,150.00 FS	*- FS
23	1		*WHEEL BEARING HOUSING LH	Not Necessary	1,070.00 FS	*- FS
24	1		*SWIVEL JOINT	Necessary	214.00 FS	*170.80 FS
25	1		*WHEEL HUB	Not Necessary	498.00 FS	*- FS
26	1		*WHEEL BEARING W FLANGE	Not Necessary	273.00 FS	*- FS
27	1		*SUSPENSION FORKS LH	Not Necessary	293.00 FS	*- FS
28	2		*COUPLING ROD	Not Necessary	258.00 FS	*- FS
29	1		*ANTI-ROLL BAR	Not Necessary	478.00 FS	*- FS
30	1		*GAS SHOCK ABSORBER	Not Necessary	323.00 FS	*- FS
31	1		*DRIVE SHAFT	Not Necessary	2,999.00 FS	*- FS
32	1		*STEERING GEAR	Not Necessary	7,318.00 FS	*- FS
33	1		*TRACK ROD	Not Necessary	109.00 FS	*- FS
34	1		*TIE ROD END LH	Not Necessary	217.00 FS	*- FS
35	1		*FRONT TYRE LH (80%)	Torn	340.00 FS	*272.00 FS
36	1		*SUNDRIES	Necessary	600.00 FS	*164.96 FS
37	1		*FRONT WISHBONE (Supplementary)	Bent	605.00 FS	*483.60 FS
38	1		*SWIVEL JOINT - RH (Supplementary)	Necessary	214.00 FS	*170.80 FS
39	1		*STONE CHIP GUARD - LH (Supplementary)	Broken	49.00 FS	*39.20 FS
40	1		*FRONT SUSPENSION CONSOLE - LH (Supplementary)	Broken	523.00 FS	*418.40 FS
41	1		*RADIATOR AIR GUIDE - LH (Supplementary)	Broken	72.00 FS	*57.20 FS
42	1		*FRONT FENDER CHROME TRIM - LH (Supplementary)	Necessary	171.00 FS	*136.40 FS
43	1		*1 SET ATTACHMENT PART FOR SILL TRIM (Supplementary)	Necessary	136.00 FS	*108.80 FS
44	1		*1 SET ADHESIVE TAPES FOR SILL TRIM (Supplementary)	Necessary	221.00 FS	*176.80 FS
45	1		*LED HEADLIGHT - LH (Supplementary)	Broken	8,416.00 FS	*6,732.80 FS
46	1		*RADIATOR AIR GUIDE - LH OUTER (Supplementary)	Broken	19.00 FS	*14.64 FS
47	1		*RADIATOR AIR GUIDE - RH OUTER (Supplementary)	Broken	19.00 FS	*14.64 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
48	1		*ALMUMINIUM RIM - LH REAR (Supplementary)	Cut	1,889.00 FS	*1,511.20 FS
49	1		*TYRE - LH REAR (Supplementary)	Torn	385.00 FS	*308.00 FS
50	1		*RUBBER VALVE (Supplementary)	Necessary	8.00 FS	*5.92 FS
51	1		*BRACKET FOR LOCK CARRIER (Supplementary)	Broken	154.00 FS	*122.80 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	42,499.70 16,315.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS	New	1,400.00	1,400.00
3	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	2,000.00
5	TO RESPRAY FRONT BUMPER	New	1,000.00	550.00
6	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
7	TO CARRY OUT PRE / POST DIAGNOSTIC CHECK	New	384.00	384.00
8	TO REMOVE AND REINSTALL LHS SILL PANEL TRIM (Supplementary)	New	1,200.00	500.00
9	TO RESPRAY LHS FRONT FENDER AND LHS SILL PANEL TRIM (Supplementary)	New	2,400.00	1,100.00
10	TO RENEW LHS REAR RIM WITH TYRE (Supplementary)	New	40.00	40.00
11	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE (Supplementary)	New	400.00	250.00
Gross Labour Cost (S\$)			14,224.00	9,624.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >