

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG22002680/TTY3E2

**Date:** 20/05/2022

### REFERENCE

Insured/Claimant: LIYAKATHALI HUMAYUNKABEER Policy No: 1900103712  
Date of Loss: 12/03/2022 Nature of Claim: OD Claim No: 0422096222SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP7162L**  
Make & Model: YAMAHA AEROX GDR155A, 155cc CVT ABS Engine No: G3J8E0104775  
Reg. Date: 28/05/2019 (Man. Year: 2019) Chassis No: MH3SG4640KJ055893  
Colour: Maroon Odometer: 56174 km  
Engine Capacity: 155 cc  
Market Value/New Car Price: S\$9,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 110/80 R14 Rear Tyre Size: 140/70 R14  
Front Left Side: IRC 5 mm Rear Left Side: IRC 5 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|--|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 3,564.30        | 1,838.20        | 1,726.10        | 48.43        |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00            |              |
| Labour                                   | 1,630.00        | 550.00          | 1,080.00        | 66.26        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>5,194.30</b> | <b>2,388.20</b> | <b>2,806.10</b> | <b>54.02</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>1,900.00</b> |                 |              |
| <b>- Excess (S\$)</b>                    | 300.00          | 300.00          | 0.00            | 0.00         |
| <b>(S\$)</b>                             | 4,894.30        | 1,600.00        | 3,294.30        | 67.31        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 342.60          | 112.00          | 230.60          | 67.31        |
| <b>Nett Amount (S\$)</b>                 | <b>5,236.90</b> | <b>1,712.00</b> | <b>3,524.90</b> | <b>67.31</b> |

### INSPECTION

Date of Assignment: 23/03/2022

Date Inspected: 05/04/2022

Estimated Period of Repair: 3.0 days

Inspected At: Bike Production (HQ)  
No 610 Serangoon Road  
Singapore 218216

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                                  | Condition     | Repairer's | Amount     |
|-----|-----|----------|--|---------------|------------|------------|
| 1   | 2   |          | *FRONT MUDGUARD LABEL ABS                    | Necessary     | 15.00 FL   | *15.00 FL  |
| 2   | 1   |          | *FRONT MUDGUARD                              | Cut           | 98.00 FL   | *98.00 FL  |
| 3   | 1   |          | *WHEEL AXLE                                  | Not Necessary | 65.00 FL   | *- FL      |
| 4   | 1   |          | *LEFT FORK ASSY                              | Not Necessary | 395.00 FL  | *- FL      |
| 5   | 1   |          | *STEERING STEM                               | Not Necessary | 220.00 FL  | *- FL      |
| 6   | 2   |          | *STEERING STEM BEARING                       | Not Necessary | 90.00 FL   | *- FL      |
| 7   | 1   |          | *HANDLE BAR                                  | Bent          | 145.00 FL  | *145.00 FL |
| 8   | 1   |          | *IU BRACKET                                  | Not Necessary | 35.00 FL   | *- FL      |
| 9   | 1   |          | *BRAKE LEVER LEFT                            | Cut           | 48.00 FL   | *48.00 FL  |
| 10  | 1   |          | *BALANCER LEFT                               | Cut           | 35.00 FL   | *35.00 FL  |
| 11  | 1   |          | *LEFT HANDLE GRIP                            | Cut           | 29.00 FL   | *29.00 FL  |
| 12  | 1   |          | *LEFT VIEW MIRROR                            | Cut           | 58.00 FL   | *58.00 FL  |
| 13  | 1   |          | *LEFT BODY COVER LABEL                       | Necessary     | 45.00 FL   | *45.00 FL  |
| 14  | 1   |          | *LEFT BODY COVER AMBLEM                      | Necessary     | 35.00 FL   | *35.00 FL  |
| 15  | 1   |          | *LEFT BODY COVER                             | Cut           | 125.00 FL  | *125.00 FL |
| 16  | 1   |          | *LEFT FLOORSTEP UNDER                        | Cut           | 95.00 FL   | *95.00 FL  |
| 17  | 1   |          | *LEFT FLOOR STEP                             | Cut           | 120.00 FL  | *120.00 FL |
| 18  | 1   |          | *AIRBOX ASSY                                 | Not Necessary | 145.00 FL  | *- FL      |
| 19  | 1   |          | *LEFT ENGINE COVER                           | Cut           | 115.00 FL  | *115.00 FL |
| 20  | 1   |          | *EXHAUST HEAT SHIELD                         | Cut           | 95.00 FL   | *95.00 FL  |
| 21  | 1   |          | *EXHAUST ASSEMBLY                            | Not Necessary | 399.00 FL  | *- FL      |
| 22  | 1   |          | *SIDE STAND                                  | Not Necessary | 65.00 FL   | -          |
| 23  | 1   |          | *MAIN STAND                                  | Not Necessary | 115.00 FL  | *- FL      |
| 24  | 1   |          | *ERP IU                                      | Cut           | 157.00 FS  | *157.00 FS |
| 25  | 1   |          | *FRONT SPORT RIM                             | Not Necessary | 350.00 FS  | *- FS      |
| 26  | 1   |          | *HEADLAMP ASSY<br>(Supplementary)            | Cracked       | 275.00 FL  | *275.00 FL |
| 27  | 2   |          | *SIDE BLACK COVER<br>(Supplementary)         | Deformed      | 130.00 FL  | *130.00 FL |
| 28  | 1   |          | *CENTER COVER<br>(Supplementary)             | Deformed      | 95.00 FL   | *95.00 FL  |
| 29  | 1   |          | *FRONT MUDGUARD REAR SIDE<br>(Supplementary) | Deformed      | 75.00 FL   | *75.00 FL  |
| 30  | 1   |          | *LEFT SIDE COVER<br>(Supplementary)          | Deformed      | 125.00 FL  | *125.00 FL |
| 31  | 1   |          | *STEP RUBBER LEFT<br>(Supplementary)         | Torn          | 45.00 FL   | *45.00 FL  |
| 32  | 1   |          | *LOWER HEADLIGHT COVER<br>(Supplementary)    | Cracked       | 65.00 FL   | *65.00 FL  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|   |          |          |
|---|----------|----------|
| Sub Total (\$\$)                                    | 3,904.00 | 2,025.00 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 339.70   | 186.80   |
| Total Parts (\$\$)                                  | 3,564.30 | 1,838.20 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's      | Amount        |
|---------------------------------|---|----------|-----------------|---------------|
| <b>Labour Items</b>             |   |          |                 |               |
| 1                               | TOWING CHARGES  | New      | 100.00          | 100.00        |
| 2                               | REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM | New      | 700.00          | 300.00        |
| 3                               | TO REMOVE, REPLACE AND BALANCE FRONT WHEEL RIM                                    | New      | 120.00          | 0.00          |
| 4                               | TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING                                     | New      | 380.00          | 0.00          |
| 5                               | TO REMOVE/REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES        | New      | 180.00          | 0.00          |
| 6                               | SUPPLEMENTARY LABOUR  | New      | 150.00          | 150.00        |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>1,630.00</b> | <b>550.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >