



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 8293H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LEFT FRONT FENDER (CONSISTENT)	BURST	1,100.00	577.10
1	LEFT FRONT FENDER SIGNAL LAMP (CONSISTENT)	CRACKED	321.00	71.00
1	LH FRONT FENDER INNER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	455.00	-
1	FRONT LEFT DOOR (CONSISTENT)	BUCKLED	1,455.00	1,219.70
1	FRONT LEFT DOOR HINGE (CONSISTENT)	DISTORTED	165.00	65.10
1	FRONT LEFT SIDE MIRROR ASSY (CONSISTENT)	SERVICEABLE	612.00	-
1	FRONT LEFT FENDER GLASS GARNISH (CONSISTENT)	BROKEN	212.00	112.00
1	FRONT LEFT RIMS (CONSISTENT)	NOT NECESSARY	650.00	-
1	FRONT LEFT LOWER ARMS (CONSISTENT)	NOT NECESSARY	355.00	-
1	FRONT LEFT WHEEL KNUCKLE (CONSISTENT)	NOT NECESSARY	395.00	-
1	FRONT LEFT WHEEL BEARING (CONSISTENT)	NOT NECESSARY	322.00	-
	LESS 10% DISCOUNT		-604.20	-204.49
			5,437.80	1,840.41
1	FRONT LEFT DOOR UEN STICKER (SN) (CONSISTENT)	NECESSARY	40.00	20.00
1	FRONT LEFT DOOR DECAL STICKER (SN) (CONSISTENT)	NECESSARY	250.00	150.00
	LESS 10% DISCOUNT		-29.00	-
			261.00	170.00
	<b><u>LABOUR</u></b>			
	TO FIX & DISMANTLE AND REMOVE DAMAGED FRONT LEFT PORTIONS, AFFECTED DAMAGED PORTION .INCLUSIVE OF THE REPAIR OF LH FRONT FENDER INNER PANEL.		1,000.00	500.00
	TO APPLY ANTI RUST COAT AND AFFECTED AREAS . (NPA)	NOT NECESSARY	-	-
	TO CHECK WIRING .(NPA)	NOT NECESSARY	-	-
	WELDING AND CUTTING OF AFFECTED PANELS ,INCLUDING CHASSIS ALIGNMENT.	NOT NECESSARY	800.00	-
	SPRAY PAINTING FOR FRONT LEFT PORTIONS AFFECTED PARTS.		1,000.00	500.00
	REFOCUSING OF THE FRONT HEADLAMP .		120.00	30.00
	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE.	NOT NECESSARY	120.00	-

Report Ref No. CC4/ASM22002682/Cpa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	3D WHEEL ALIGNMENT.	NOT NECESSARY	180.00	-
	TO APPLY WATERPROOFING SEALER ON END PANELS. (NPA)	NOT NECESSARY	-	-
			3,220.00	1,030.00
<b>GRAND TOTAL</b>			<b>8,918.80</b>	<b>3,040.41</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,400.00</b>

Report Ref No. CC4/ASM22002682/Cpa3q2

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.