

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: GBG8293H
Chassis No:
Engine No:

Report No :
Date : 23.03.2022

Replacement of Damaged Parts

S/No.	QTY	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Left Front Fender	Damaged BUC	\$ 1,100.00	577.10 \$ 990.00
2	1	Left Front Fender Signal Lamp	Broken CRA	\$ 321.00	271 \$ 288.90
3	1	LH Front Fender Inner Panel	Impacted XR	\$ 455.00	X \$ 409.50
4	1	Front Left Door	Damaged BUC	\$ 1,455.00	1219.10 \$ 1,309.50
5	1	Front Left Door Hinge	Distored	\$ 165.00	65.10 \$ 148.50
6	1	Front Left Side Mirror Assy	Damaged XSC	\$ 612.00	X \$ 550.80
7	1	Front Left Fender Glass Garnish	Broken	\$ 212.00	112 \$ 190.80
8	1	Front Left Door UEN Sticker	Necessary	\$ 40.00	20.50 \$ 36.00
9	1	Front Left Door Decal Sticker	Necessary	\$ 250.00	150.50 \$ 225.00
10	1	Front Left Rims	Impacted	\$ 650.00	X \$ 585.00
11	1	Front Left Lower Arms	Impacted	\$ 355.00	X \$ 319.50
12	1	Front Left Wheel Knuckle	Impacted	\$ 395.00	X \$ 355.50
13	1	Front Left Wheel Bearing	Impacted	\$ 322.00	X \$ 289.80
				\$ 6,332.00	\$ 5,065.60

Total (Parts): \$ 6,332.00 -10% \$ 5,065.60

Labour Charges

14	To fix & dismantle and remove damaged Front Left Portions; affected damaged portion.	\$ 1,000.00	500
15	To apply anti rust coat and affected areas	\$ -	
16	To check wiring	\$ -	
17	Welding and cutting of affected panels, including chassis alignment.	\$ 800.00	X
18	Spray painting for Front Left Portions affected parts	\$ 1,000.00	500
19	Refocusing of the front headlamp	\$ 120.00	30
20	Diagnose ECU system and reset error code.	\$ 120.00	X
21	3D Wheel Alignment	\$ 180.00	X
22	To Apply Waterproofing sealer on End Panels		

Total Labour: \$ 3,220.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 8,285.60

Less 20% \$ 6,628.48

AMM PTE LTD

Page 2 of 3

4 days

P - \$1840.41

S/N - 170

L - 1030

YS - \$2400.00