

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002685/UQY3N2**Date:** 31/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00043742100

Claimant Vehicle No : SKU4651D **Insured Vehicle No :** SJW3780Y

Date of Loss: 18/03/2022 Nature of Claim: TP Claim No: SNM22D201921/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU4651D**

Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZX979438

Reg. Date: 28/10/2009 (Man. Year: 2009) Chassis No: MR053HY9305132575

Colour: Grey Odometer: 316473 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,529.22	1,363.07	4,166.15	75.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,280.00	1,320.00	50.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,129.22	2,643.07	5,486.15	67.49
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	8,129.22	2,100.00	6,029.22	74.17

INSPECTION

Date of Assignment: 23/03/2022

Date Inspected: 23/03/2022 Inspected At: 15 Kaki Bukit Road 4
#01-05/53 Bartley Biz Centre
REPAIRER: ASIA MOTORSPORTS SOLUTION
PTE LTD

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2022)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU4651D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed/Warped	589.20 FL	*488.10 FL
2	2		*REAR BUMPER BRACKET	Not Necessary	176.80 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Necessary	177.20 FL	*96.00 FL
4	1		*REAR BOOTLID ASSY	Repair	693.80 FL	*- FL
5	1		*REAR BOOTLID WEATHERSTRIP	Not Necessary	168.70 FL	*- FL
6	1		*REAR BOOTLID LOCK MECHANISM	Not Necessary	106.20 FL	*- FL
7	1		*REAR BOOTLID LOCK CATCH	Not Necessary	62.40 FL	*- FL
8	1		*REAR BOOTLID LOCK CYLINDER	Not Necessary	195.10 FL	*- FL
9	1		*REAR BOOTLID OUTER GARNISH	Not Necessary	128.60 FL	*- FL
10	1		*REAR BOOTLID CENTRE LOGO	Not Necessary	68.30 FL	*- FL
11	1		*REAR BOOTLID E EMBLEM	Not Necessary	62.20 FL	*- FL
12	1		*REAR BOOTLID SPORT EMBLEM	Not Necessary	69.80 FL	*- FL
13	1		*REAR BOOTLID VIOS EMBLEM	Not Necessary	65.90 FL	*- FL
14	1		*REAR LEFT TAILLAMP	Not Necessary	468.30 FL	*- FL
15	1		*REAR RIGHT TAILLAMP	Not Necessary	468.30 FL	*- FL
16	1		*REAR END LOWER PANEL	Repair	483.20 FL	*- FL
17	1		*REAR END LOWER PANEL TOP GARNISH	Not Necessary	88.30 FL	*- FL
18	10		*REAR BUMPER CLIPS	Necessary	60.00 FS	*45.00 FS
19	4		*REAR END LOWER PANEL TOP GARNISH CLIPS	Not Necessary	35.00 FS	*- FS
20	1		*REAR END LOWER PANEL SEALANT	Not Necessary	140.00 FS	*- FS
21	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
22	1		*REAR NO PLATE WITH GARNISH	Not Necessary	100.00 FS	*- FS
23	1		*REAR BUMPER LOWER DIFFUSER	Cracked	880.00 FS	*680.00 FS
24	1		*REAR BUMPER LOWER DIFFUSER SEALANT	Not Necessary	100.00 FS	*- FS
25	10		*REAR BUMPER LOWER DIFFUSER CLIPS	Not Necessary	50.00 FS	*- FS
26	1		*REAR LEFT SIDE LOWER SPOILER	No such part	350.00 FS	*- FS
27	1		*REAR RIGHT SIDE LOWER SPOILER	No such part	350.00 FS	*- FS
28	1		*REAR LEFT SIDE LOWER SPOILER SEALANT	Not Necessary	40.00 FS	*- FS
29	1		*REAR RIGHT SIDE LOWER SPOILER SEALANT	Not Necessary	40.00 FS	*- FS
30	4		*REAR BOOTLID OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					6,547.30	1,509.10
- List Item Discount on L Items 25.00/25.00% (\$\$)					1,018.08	146.03
Total Parts (\$\$)					5,529.22	1,363.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,000.00	400.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,000.00	750.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
4	TO REMOVE AND INSTALL REAR BOOTLID LOCK MECHANISM	New	80.00	0.00
5	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	150.00	60.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	140.00	0.00
7	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
8	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$\$)			2,600.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >