

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22002688/TVY3N2**Date:** 18/05/2022**REFERENCE**

Handling Insurer:	ECICS Limited	Policy No:	MPC21A00039900
Claimant Vehicle No :	SMX6839C	Insured Vehicle No :	SLE731E
Date of Loss:	18/03/2022	Nature of Claim:	TP
		Claim No:	DMPC2200113H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX6839C	Engine No:	F1993853B48B20A
Make & Model:	BMW 318i, 2.0 (A)	Chassis No:	WBA72DY000FK61322
Reg. Date:	26/01/2021 (Man. Year: 2020)	Odometer:	21058 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,038.85	7,592.80	9,446.05	55.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,585.00	4,150.00	2,435.00	36.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,623.85	11,742.80	11,881.05	50.29
+ GST 7.00/7.00% (S\$)	1,653.67	822.00	831.67	50.29
Nett Amount (S\$)	25,277.52	12,564.80	12,712.72	50.29

INSPECTION

Date of Assignment:	23/03/2022		
Date Inspected:	24/03/2022	Inspected At:	BIS Automobiles Pte Ltd (HQ) 30 Teban Gardens Crescent Singapore 608927
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$8,503.50 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2022)
Parts:	143	BMW 318i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX6839C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT AXLE SUPPORT	*Check	1,404.00 FS	*- FS
2	1		*TENSION STRUT WITH HYDR,MOUNT,RIGHT	Dented	286.15 FS	*286.15 FS
3	1		*WISHBONE,BOTTOM,WITH RUBBER MOUNT,RIGHT	Bent	343.35 FS	*343.35 FS
4	1		*WHEEL HUB WITH BEARING	Bent	431.85 FS	*431.85 FS
5	1		*CARRIER,RIGHT (RWD)	Bent	499.05 FS	*499.05 FS
6	4		*SPHERICAL COLLAR SCREW (M12X1.25X45)	Necessary	32.20 FS	*32.20 FS
7	1		*SUPPORT BEARING FRONT	*Check	234.95 FS	*- FS
8	1		*FRONT RIGHT SPRING STRUT	*Check	537.95 FS	*- FS
9	1		*SWING SUPPORT,FRONT,RIGHT	*Check	105.15 FS	*- FS
10	1		*STABILIZER FRONT WITH RUBBER MOUNTING	*Check	411.70 FS	*- FS
11	1		*STEERING GEAR,ELECTRIC	*Check	5,244.75 FS	*- FS
12	1		*RIGHT TIE ROD	Bent	313.05 FS	*313.05 FS
13	1		*LEFT TIE ROD	Not Necessary	313.05 FS	*- FS
14	1		*WISHBONE,BOTTOM,WITH RUBBER,LEFT	Not Necessary	343.35 FS	*- FS
15	1		*TENSION STRUT WITH HYDR,MOUNT,LEFT	Not Necessary	286.15 FS	*- FS
16	1		*DISK WHEEL	Cut	999.40 FS	*999.40 FS
17	1		*HUB CAP WITH CHROME EDGE (BMW)	*Check	29.80 FS	*- FS
18	1		*HEADLIGHT LED,AHL RIGHT	Cut	3,397.70 FS	*3,397.70 FS
19	1		*PANEL,BUMPER,PRIMED,FRO	Deformed	1,089.85 FS	*1,089.85 FS
20	1		*SUPPORT RIGHT	*Check	83.85 FS	*- FS
21	1		*GRILLE,SIDE,CLOSED,RIGHT (BASIS)	Cut	79.60 FS	*79.60 FS
22	1		*AIR INLET FINISHER,RIGHT	*Check	68.20 FS	*- FS
23	1		*ULTRASONIC S	*Check	383.15 FS	*- FS
24	4		*DECOUPLING RING	Necessary	20.60 FS	*20.60 FS
25	1		*SUNDRIES	Necessary	100.00 FS	*100.00 FS
					Total Parts (\$\$)	17,038.85 7,592.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER AND ATTACHMENTS INCLUDE MAKING GOOD THE FRONT RH FENDER AND KNOCKING OUT DENTS CAUSED BY THE ACCIDENT	New	2,160.00	1,080.00
2	TO SPRAY PAINT FRONT BUMPER AND FRONT RH FENDER	New	1,675.00	850.00
3	TO REPLACE PDC SENSORS AND CONNECTORS INCLUDE RESETTING AND CONDUCTING CHECKS FOR PROPER FUNCTION	New	350.00	280.00
4	TO SUPPLY FRONT RH WHEEL RIM (NPA)	New	0.00	0.00
5	TO SUPPLY FRONT RH TIRE (NPA) *Check	New	0.00	0.00
6	TO REPLACE FRONT RH TIRE OR WHEEL RIM INCLUDE WHEEL BALANCING	New	100.00	100.00
7	TO CONDUCT CHECKS ON STEERING GEOMETRY INCLUDING WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	450.00	360.00
8	TO REMOVE AND INSTALL FRONT BRAKE DISCS,BRAKE PADS,BRAKE HOSES AND BRAKE CALIPERS INCLUDE BLEEDING OF BRAKE SYSTEM,CONDUCTING BRAKE TESTS AND CHECKS FOR LEAK	New	450.00	360.00
9	TO REMOVE AND INSTALL FRONT RH SUSPENSION FOR INSPECTION INCLUDE REPLACEMENT OF DAMAGED PARTS AND CONDUCTING CHECKS FOR PROPER FUNCTION	New	900.00	720.00
10	TO CARRY OUT DIAGNOSIS TESTS	New	500.00	400.00
Gross Labour Cost (\$\$)			6,585.00	4,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >