

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT MS FIRST CAPITAL INSURANCE LTD Ref: CS3/FCI22002700/Vqy3e2 36 ROBINSON ROAD #16-01 CITY HOUSE Date: 06/04/2022 SINGAPORE 068877 Code: FCI2 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. PC 2947A SBS 6431B Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. D22000838MFBP/GA/EL Excess (\$) 0.00 HARMINDER KAUR **Assign From Assign Date** 23/03/2022 **Vehicle Particulars & Condition** 2. TOYOTA HIACE COMMUTER Make & Model c.c 2982 HIDDEN 2014 Engine No. Year of Reg. KDH2230020988 WHITE Chassis No. Colour Odometer 213018 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15C **DURATURN** 5 mm **DURATURN** L/H Front Tyre 195 R15C 5 mm 195 R15C DURATURN R/H Rear Tyre 5 mm **DURATURN** 5 mm L/H Rear Tyre 195 R15C 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS. 5. **General Information** 21/03/2022 24/03/2022 (12:00 PM) Inspect Date / Time Accident Date **GARAGE 13 PTE LTD** Survey held at 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$32,000.00

Report Ref No. CS3/FCI22002700/Vqy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser