



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 2794A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED	1,098.00	1,098.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	228.00	-
1	FRONT BUMPER SPONGE	CRACKED	148.00	148.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	578.00	-
1	FRONT BUMPER TOP BEAM	CRACKED	209.00	209.00
1	FRONT GRILLE	CUT	485.00	485.00
1	FRONT GRILLE LOGO	CUT	112.00	112.00
2	HEADLAMP @\$1955.00	NOT NECESSARY	3,910.00	-
	LESS 10% DISCOUNT		-	-205.20
			6,768.00	1,846.80
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT NUMBER PLATE (SN)	DENTED	30.00	30.00
1	FRONT NUMBER PLATE HOLDER (SN)	DEFORMED	30.00	30.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	FRONT GRILLE CLIPS (SN)	NECESSARY	30.00	30.00
			140.00	140.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		500.00	250.00
	SPRAY PAINTING.		500.00	250.00
	WIRING.		50.00	30.00
			1,050.00	530.00
<b>GRAND TOTAL</b>			<b>7,958.00</b>	<b>2,516.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,000.00</b>

Report Ref No. CS/AGI22002701/Any3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.