

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG22002704/AVCE2**Date:** 21/11/2022REFERENCE

Insured/Claimant:	CHAN KIM LENG	Policy No:	2100413971		
Date of Loss:	17/03/2022	Nature of Claim:	OD	Claim No:	0856467465SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGM1800A</b>		
Make & Model:	AUDI A4, 1.8 TFSI MU Attraction (A)	Engine No:	CJE100729
Reg. Date:	29/05/2015 (Man. Year: 2015)	Chassis No:	WAUZZZ8K2FA117375
Colour:	Black	Odometer:	139135 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	25,393.90	12,282.40	13,111.50	51.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,444.00	4,842.00	8,602.00	63.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>38,837.90</b>	<b>17,124.40</b>	<b>21,713.50</b>	<b>55.91</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>14,000.00</b>		
<b>- Excess (S\$)</b>	400.00	400.00	0.00	0.00
<b>(S\$)</b>	38,437.90	13,600.00	24,837.90	64.62
<b>+ GST 7.00/7.00% (S\$)</b>	2,690.65	952.00	1,738.65	64.62
<b>Nett Amount (S\$)</b>	<b>41,128.55</b>	<b>14,552.00</b>	<b>26,576.55</b>	<b>64.62</b>

INSPECTION

Date of Assignment:	24/03/2022		
Date Inspected:	23/03/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,725.00 FS	*2,180.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	271.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENTS	Not Necessary	254.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE LOWER CENTRE	Not Necessary	151.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT UPPER CENTRE	Cracked	271.00 FS	*173.60 FS
6	1		*FRONT BUMPER SUPPORT ELEMENT UPPER	Not Necessary	66.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,205.00 FS	*964.00 FS
8	2		*FRONT BUMPER AIR GUIDE GRILLE LH / RH	Not Necessary	302.00 FS	*- FS
9	2		*FRONT WHEEL SPOILER FRONT LH / RH	Not Necessary	114.00 FS	*- FS
10	1		*FRONT REINFORCEMENT BEAM	Dented	985.00 FS	*787.60 FS
11	1		*FRONT BUMPER FOAM FILLER	Cracked	139.00 FS	*110.80 FS
12	2		*FRONT BUMPER SUPPORT	Not Necessary	29.00 FS	*- FS
13	2		*FRONT BUMPER GUIDE SECTION LH / RH	Not Necessary	82.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Deformed	143.00 FS	*114.00 FS
15	1		*FRONT BUMPER BRACKET LH	Not Necessary	255.00 FS	*- FS
16	1		*STICKER SIGNAGE CAUTION HIGH VOLTAGE	Necessary	16.00 FS	*12.40 FS
17	1		*STICKER SIGNAGE FOR AIR CONDITIONER	Necessary	34.00 FS	*26.96 FS
18	1		*SIGNAL HORN HIGH TONE LH	Not Necessary	214.00 FS	*- FS
19	1		*SPRING SHACKLE HIGH TONE LH	Not Necessary	28.00 FS	*- FS
20	2		*FRONT FENDER LH / RH	Not Necessary	2,222.00 FS	*- FS
21	1		*FRONT FENDER ATTACHMENTS	Not Necessary	60.00 FS	*- FS
22	2		*FRONT FENDER BRACE LOWER LH / RH	Not Necessary	264.00 FS	*- FS
23	2		*FRONT FENDER BRACKET FRONT LH / RH	Not Necessary	118.00 FS	*- FS
24	1		*POP RIVET (8PCS)	Necessary	31.00 FS	*24.32 FS
25	2		*FRONT WHEEL HOUSING LINERS LH / RH	Not Necessary	520.00 FS	*- FS
26	1		*STONE CHIP GUARD LH	Not Necessary	82.00 FS	*- FS
27	1		*ADHESIVE TAPE	Not Necessary	59.00 FS	*- FS
28	1		*STONE CHIP GUARD RH	Not Necessary	82.00 FS	*- FS
29	1		*ADHESIVE TAPE	Not Necessary	59.00 FS	*- FS
30	1		*BONNET	Dented	3,414.00 FS	*2,731.20 FS
31	1		*BONNET PROTECTIVE FILM FRONT	Not Necessary	51.00 FS	*- FS
32	1		*BONNET ATTACHMENTS PARTS	Not Necessary	176.00 FS	*- FS
33	2		*BONNET LID HINGE LH / RH	Bent	166.00 FS	*131.68 FS
34	1		*BONNET CATCH HOOK	Not Necessary	155.00 FS	*- FS
35	1		*BONNET LID LOCK W MICRO SWITCH	Not Necessary	228.00 FS	*- FS
36	1		*BONNET LID LOCK CABLE FRONT	Not Necessary	55.00 FS	*- FS
37	1		*BONNET EDGE PROTECTION FRONT	Necessary	31.00 FS	*24.72 FS
38	1		*BONNET LOCK COVER	Not Necessary	26.00 FS	*- FS
39	1		*HEADLIGHT MOUNTING LH / RH	N/s cracked	264.00 FS	*105.20 FS
40	1		*HEADLIGHT BRACKET LH / RH	N/s cracked	236.00 FS	*94.00 FS
41	2		*HEADLIGHT DISCHARGE LAMP LH / RH	Cracked	4,984.00 FS	*3,987.20 FS
42	2		*HEADLIGHT LIFT CYLINDER LH / RH	Not Necessary	462.00 FS	*- FS
43	1		*HEADLIGHT LIFT CYLINDER HOSE ROLLERS	Not Necessary	204.00 FS	*- FS
44	1		*AIRCON CONDENSER	Dented	816.00 FS	*652.80 FS
45	1		*AIRCON CONDENSER BRACKET	Not Necessary	21.00 FS	*- FS
46	1		*CHARGE AIR COOLER	Not Necessary	628.00 FS	*- FS
47	1		*RADIATOR	Not Necessary	1,442.90 FS	*- FS
48	1		*RADIATOR LOWER SUPPORT	Not Necessary	43.00 FS	*- FS
49	1		*AIR GUIDE LH / RH	N/s deformed	84.00 FS	*33.28 FS
50	6		*READY MIX COOLANT 1.0L	Not Necessary	282.00 FS	*- FS
51	1		*INTAKE MANIFOLD FRONT	Not Necessary	107.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*BELLOWS RESONATOR	Not Necessary	119.00 FS	*- FS
53	1		*WATER DEFLECTOR STRIP RH	Not Necessary	75.00 FS	*- FS
54	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
55	1		*SUNDRIES	Necessary	400.00 FS	*68.64 FS
56	1		*COVER FOR PLENUM CHAMBER	Not Necessary	83.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$)</b>	<b>25,393.90</b>	<b>12,282.40</b>
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT,HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS	New	1,400.00	480.00
3	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDER AND RHS UPPER A-PILLAR	New	5,000.00	1,810.00
4	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
5	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	500.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	1,500.00
<b>Gross Labour Cost (S\$)</b>			<b>13,444.00</b>	<b>4,842.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >