

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22002710/AQY3M4**Date:** 03/11/2022REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP317411
Claimant Vehicle No :	GBF5496P	Insured Vehicle No :	SML8181R
Date of Loss:	21/03/2022	Nature of Claim:	TP
		Claim No:	MPC03261/ANA

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF5496P		
Make & Model:	NISSAN URVAN, 3.0 D MICROBUS 4DR 4A/T ABS AIRBAG (A)	Engine No:	ZD30131093K
Reg. Date:	07/05/2008 (Man. Year: 2007)	Chassis No:	JN1TG4E25Z0770003
Colour:	White	Odometer:	243647 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,689.00	5,260.70	4,428.30	45.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,450.00	1,550.00	51.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,689.00	6,710.70	5,978.30	47.11
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	12,689.00	5,300.00	7,389.00	58.23

INSPECTION

Date of Assignment: 24/03/2022

Date Inspected: 24/03/2022 Inspected At:

BEST SOLUTION AUTOCARE PTE LTD
53 UBI AVE 1
#03-01 PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Nov 2022)	
Parts:	N/A	NISSAN URVAN 3.0 D MICROBUS 4DR 4A/T ABS AIRBAG (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for GBF5496P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	858.00 F	*684.00 FL
2	1		*FRONT BUMPER CLIP	Necessary	30.00 F	*30.00 FL
3	1		*SET FRONT BUMPER SIDE RETAINER	O/s Damaged	216.00 F	*108.00 FL
4	1		*FRONT BUMPER FOG LAMP	Not Necessary	388.00 F	*- FL
5	1		*FRONT BUMPER FOG LAMP GARNISH	Cut	165.00 F	*165.00 FL
6	1		*O/S FRONT DOOR	Dented	1,559.00 F	*1,315.00 FL
7	1		*FRONT DOOR STICKER	Necessary	40.00 F	*40.00 FL
8	1		*O/S FRONT SIDE LAMP	Cracked	279.00 F	*279.00 FL
9	1		*O/S HEADLAMP	Cracked	745.00 F	*482.00 FL
10	1		*FRONT GRILLE	Cracked	655.00 F	*412.00 FL
11	1		*O/S FRONT TYRE	Not Necessary	250.00 F	*- FL
12	1		*O/S FRONT DOORSTEP GARNISH	Deformed	435.00 F	*205.00 FL
13	1		*O/S FRONT SIDE FENDER	Buckled	785.00 F	*375.00 FL
14	1		*FRONT LOWER ARM	Bent	285.00 F	*285.00 FL
15	1		*FRONT UPPER ARM	Not Necessary	487.00 F	*- FL
16	1		*FRONT ABSORBER	Bent	225.00 F	*225.00 FL
17	1		*FRONT TIE ROD	Bent	135.00 F	*135.00 FL
18	1		*FRONT BALL JOINT HEAD	Not Necessary	128.00 F	*- FL
19	1		*FRONT LINKAGE	Not Necessary	69.00 F	*- FL
20	1		*FRONT ANTI ROLL BAR BUSH	Not Necessary	25.00 F	*- FL
21	1		*FRONT WHEEL BEARING HUB	Damaged	783.00 F	*430.00 FL
22	1		*FRONT KNUCKLE ARM	Damaged	453.00 F	*453.00 FL
23	1		*O/S FRONT FENDER INNER SHIELD	Not Necessary	98.00 F	*- FL
24	1		*SET O/S FRONT FENDER INNER SHIELD CLIP	Not Necessary	30.00 F	*- FL
25	1		*O/S FRONT UPPER DOOR HINGE	Not Necessary	93.00 F	*- FL
26	1		*O/S FRONT LOWER DOOR HINGE	Not Necessary	93.00 F	*- FL
27	1		*O/S FRONT RIM	Cut	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,689.00	5,823.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	562.30
Total Parts (\$)	9,689.00	5,260.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS, PANEL BEAT, REPAIR	New	1,200.00	600.00
2	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	500.00
3	ANTI RUST	New	180.00	40.00
4	TRANSFER DOOR FITTINGS	New	150.00	80.00
5	WIRING CHECK	New	80.00	30.00
6	WHEEL ALIGNMENT	New	120.00	80.00
7	UNDERCARRIAGE	New	120.00	120.00
8	REMOVE AND REFIX WINDOW GLASS	New	150.00	0.00
Gross Labour Cost (\$)			3,000.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >