



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 7650X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DENTED / CRACKED	663.55	663.55
	LESS 10% DISCOUNT		-66.35	-66.35
			597.20	597.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
			60.00	60.00
	<b><u>LABOUR</u></b>			
	COATING FOR AFFECTED AREAS.		240.00	60.00
	LABOUR CHARGES TO REMOVE, REFIX, REPLACE & READJUST FRONT ACCIDENT AREAS & ETC.		300.00	200.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER & ETC.		300.00	220.00
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	NOT NECESSARY	100.00	-
			940.00	480.00
<b>GRAND TOTAL</b>			<b>1,597.20</b>	<b>1,137.20</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,137.20</b>

Report Ref No. CS/FCI22002713/Kvy3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.