

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22002715/UEA3Q2**Date:** 09/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220013939
<b>Claimant Vehicle No :</b>	PC1701Z	<b>Insured Vehicle No :</b>	SDK1238U
Date of Loss:	21/03/2022	Nature of Claim:	TP
		Claim No:	2303651057SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>PC1701Z</b>	Engine No:	1KD2248895
Make & Model:	TOYOTA HIACE, 3.0 D High-roof 14 Seater (A)	Chassis No:	JTFST22P000015627
Reg. Date:	19/12/2012 (Man. Year: 2012)	Odometer:	213088 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,376.60	900.22	1,476.38	62.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	420.00	990.00	70.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,786.60</b>	<b>1,320.22</b>	<b>2,466.38</b>	<b>65.13</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,050.00</b>		
<b>(S\$)</b>	3,786.60	1,050.00	2,736.60	72.27
<b>+ GST 7.00/7.00% (S\$)</b>	265.06	73.50	191.56	72.27
<b>Nett Amount (S\$)</b>	<b>4,051.66</b>	<b>1,123.50</b>	<b>2,928.16</b>	<b>72.27</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,425.50</b>		

INSPECTION

Date of Assignment:	24/03/2022		
Date Inspected:	24/03/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	2.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*HEADLAMP FRONT N/S	Scratched	700.00 FL	*700.00 FL	
2	1		*HEADLAMP FRONT BRACKET	Not Necessary	150.00 FL	*- FL	
3	1		*FRONT BUMPER	Cut	500.30 FL	*500.30 FL	
4	1		*FRONT BUMPER SIDE BRACKET N/S	Not Necessary	180.00 FL	*- FL	
5	1		*FRONT DOOR N/S	Repair	1,638.50 FL	*- FL	
					<b>Sub Total (\$\$)</b>	<b>3,168.80</b>	<b>1,200.30</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	792.20	300.08
					<b>Total Parts (\$\$)</b>	<b>2,376.60</b>	<b>900.22</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE FRONT AFFECTED PORTION	New	700.00	200.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTEN FRONT OF THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	650.00	200.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
			<b>Gross Labour Cost (\$\$)</b>	<b>420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >