

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: PC17017  
 at Workshop m/s: Tankon 1.45  
 of \_\_\_\_\_  
 Insured: SKD1238U  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \$12k.  
 IDAC Accident Rport: Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: 2 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS 3 3926  
 Date: \_\_\_\_\_ Person Contacted: MA 7697  
 Vehicle: IN / OUT

Veh No: PC17017 Yr Regn: 19/12/12  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CAT hroof  
 Make: Toyota hiace c.c 2982  
 Colour: White A/C: Insured / Std / NI / NA  
 Sp. Reading: 213088 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTFST22P000015627  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: NH / S/Rim / STD A/Rim or  
 Tyre Size: F: 195 R 15  
 R: Yoko  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front 6 mm Rear 6 mm  
 R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 21/3/22 D.O.I. 24/3/22  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
N/S Frt.  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
NO SI work until 18-12-2022  
29/3/22 4/5 @ 1050 informed willian

Date/Time, File Pass to?  : Preli. Report  : Final Report  
 Date/Time, File Return to? \_\_\_\_\_  
 Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_ Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_)  : S + RS, \_\_\_\_\_  
 : Interview (\$ \_\_\_\_\_)  : Photos  
 : Tech. Invs (\$ \_\_\_\_\_)  : Others  
 : Weekend (\$ \_\_\_\_\_)  : \_\_\_\_\_  
 Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$) \_\_\_\_\_ )  
 TOTAL \_\_\_\_\_



廣林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKD1238U  
Date of Accident : 21 March 2022

Messrs Lioncity Travel Transport Services

Date : 23 March 2022

**Estimate To Repair PC1701Z - Toyota HIACE HIGHROOF AUTO 14**  
Chassis No : JTFST22P000015627

S/No	Quantity	Description	Amount
<b>LIST ITEMS</b>			
01	1 pc	headlamp front n/s <i>SCA</i>	\$ 700.00
02	1 pc	headlamp front bracket <i>17</i>	\$ 150.00
03	1 pc	front bumper <i>CU7</i>	\$ 500.30
04	1 pc	front bumper side bracket n/s <i>17</i>	\$ 180.00
05	1 pc	front door n/s <i>R</i>	\$ 1,638.50
			\$ 3,168.80
Less 25 %			\$ 792.20
			\$ 2,376.60
<b>LABOUR &amp; MISC. CHARGES</b>			
01		Putty and spray painting of the front affected portion.	\$ 700.00
02		Panel beating, knocking and straighten front of the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 650.00
03		To check electrical lighting concerned.	\$ 60.00
			\$ 1,410.00
Total			\$ 3,786.60

*not allowed here*  
*2/5 \$1050*

*2 days*  
*take 9 hrs. After repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*P- 1200.30*  
*25%*  
*P- 900.22*  
*420*  
*L- 1320.22*  
*20%*  
*1050*