

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002718/UPA3Q2**Date:** 23/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800142789
Claimant Vehicle No :	SKW7815T	Insured Vehicle No :	SMF8982C
Date of Loss:	23/03/2022	Nature of Claim:	TP
		Claim No:	8032236384SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW7815T	Engine No:	L15B4024693
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11104693
Reg. Date:	16/11/2015 (Man. Year: 2015)	Odometer:	102498 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,188.32	5,959.04	3,229.28	35.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	2,190.00	1,780.00	44.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,158.32	8,149.04	5,009.28	38.07
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	13,158.32	6,500.00	6,658.32	50.60
+ GST 7.00/7.00% (S\$)	921.08	455.00	466.08	50.60
Nett Amount (S\$)	14,079.40	6,955.00	7,124.40	50.60
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,706.00		

INSPECTION

Date of Assignment:	24/03/2022	
Date Inspected:	24/03/2022	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	653.10 FL	*653.10 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	50.40 FL	*- FL
3	2		*REAR BUMPER SIDE	Repair	423.60 FL	*- FL
4	1		*REAR BUZZER SENSOR	Not Necessary	95.00 FL	*- FL
5	1		*REAR BUMPER UNDERCOVER	Deformed / Warped	218.70 FL	*218.70 FL
6	1		*ANTENNA ASSY -SMARTKEY	Not Necessary	93.00 FL	*- FL
7	1		*TAILGATE	Badly Dented	1,197.30 FL	*997.30 FL
8	1		*SET TAILGATE GLASS MOULDING	Necessary	128.30 FL	*128.30 FL
9	2		*TAILGATE LAMP	Cracked	731.40 FL	*640.00 FL
10	1		*TAILGATE GARNISH	Not Necessary	286.70 FL	*- FL
11	1		*TAILGATE TRIM BOARD	Deformed / Torn	353.60 FL	*353.60 FL
12	1		*TAILGATE LOCK	Bent	168.00 FL	*168.00 FL
13	1		*TAILGATE WEATHERSTRIP	Twisted	155.80 FL	*155.80 FL
14	1		*TAILGATE LOGO	Not Necessary	37.00 FL	*- FL
15	1		*TAILGATE VEZEL EMBLEM	Necessary	39.00 FL	*39.00 FL
16	1		*REAR END PANEL	Dented	562.70 FL	*562.70 FL
17	1		*REAR END PANEL GARNISH	Twisted	96.60 FL	*96.60 FL
18	2		*REAR FENDER INNER TRIM	Deformed / Twisted	721.80 FL	*721.80 FL
19	1		*REAR COMPARTMENT BOARD	Warped / Torn	256.70 FL	*256.70 FL
20	1		*REAR COMPARTMENT SPONGE	Torn	266.70 FL	*266.70 FL
21	1		*REAR COMPARTMENT PANEL	Repair	959.60 FL	*- FL
22	2		*TAILLAMP	Cracked	1,173.40 FL	*936.00 FL
23	2		*REAR FENDER ARCH GARNISH	Torn	417.00 FL	*417.00 FL
24	1		*SET REAR BUMPER REFLECTOR	Cracked	400.00 FS	*200.00 FS
25	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
26	1		*SET REAR BUMPER UNDERCOVER CLIPS	Necessary	50.00 FS	*50.00 FS
27	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
28	1		*SET TAILGATE BODY SEALANT	Necessary	80.00 FS	*40.00 FS
29	1		*SET TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
30	1		*SET TAILGATE GLASS INNER SEAL	Necessary	45.00 FS	*40.00 FS
31	1		*SET TAILGATE TRIM BOARD CLIPS	Necessary	100.00 FS	*50.00 FS
32	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	100.00 FS	*- FS
33	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
34	1		*SET REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
35	1		*SET REAR COMPARTMENT RUBBER INSULATOR	Not Necessary	350.00 FS	*- FS
36	1		*SET TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*SET REAR FENDER ARCH GARNISH CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,005.40	7,281.30
- List Item Discount on L Items 20.00/20.00% (\$)	1,817.08	1,322.26
Total Parts (\$)	9,188.32	5,959.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHT AND WIRING	New	50.00	20.00
2	WATERTEST TO CHECK FOR LEAKAGE	New	50.00	0.00
3	ANTI-RUST	New	150.00	60.00
4	TO APPLY BODY SEALANT ON BODY JOINTS	New	150.00	50.00
5	REMOVE/REFIT INNER TRIMS TO FACILITATE REPAIR	New	150.00	80.00
6	TRANSFER TAILGATE GLASS	New	120.00	120.00
7	TRANSFER TAILGATE PARTS	New	120.00	60.00
8	INSTALL REVERSE SENSOR	New	80.00	50.00
9	INSTALL REVERSE CAMERA	New	150.00	0.00
10	TO DIAGNOSE AND REPROGRAM	New	250.00	0.00
11	LABOUR PANEL BEATING	New	1,200.00	800.00
12	SPRAY PAINTING	New	1,500.00	950.00
Gross Labour Cost (\$\$)			3,970.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >