

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG22002720/EPA3Q2**Date:** 20/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100508499
Claimant Vehicle No :	SJX2146E	Insured Vehicle No :	SLN3122X
Date of Loss:	07/03/2022	Nature of Claim:	TP
		Claim No:	1305354999SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX2146E	Engine No:	G4KEAH714826
Make & Model:	KIA SORENTO, 2.4 GDI HID S/R (A)	Chassis No:	KNAKU811MA5082782
Reg. Date:	25/05/2010 (Man. Year: 2010)	Odometer:	220760 km
Colour:	Grey		
Engine Capacity:	2359 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,232.00	3,619.60	2,612.40	41.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,450.00	3,670.00	2,780.00	43.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,682.00	7,289.60	5,392.40	42.52
+ GST 7.00/7.00% (S\$)	887.74	510.27	377.47	42.52
Nett Amount (S\$)	13,569.74	7,799.87	5,769.87	42.52
+ Car Rental (S\$)		3,081.60		
Nett Liability (S\$)		10,881.47		

INSPECTION

Date of Assignment:	24/03/2022	
Date Inspected:	24/03/2022	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	9.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*LAMP ASSY -HEAD ,LH	Not Necessary	1,696.80 FS	*- FS
4	1		*LAMP ASSY -REAR COMBINATION ,LH	Not Necessary	566.40 FS	*- FS
5	1		*COVER -FR BUMPER UPR	Dented	541.60 FS	*541.60 FS
6	1		*MOULDING -FRONT BUMPER A/INTAKE	Broken	21.60 FS	*21.60 FS
7	1		*COVER -FR BUMPER LWR	Broken	588.00 FS	*588.00 FS
8	1		*COVER -BLANKING FRT FOG ,RH	Cut	21.60 FS	*21.60 FS
9	1		*BRACKET -FR BUMPER SIDE SUPT RH	Not Necessary	20.80 FS	*- FS
10	1		*ABSORBER -FRONT BUMPER ENERGY	Broken	84.80 FS	*84.80 FS
11	1		*GRILLE ASSY -RADIATOR	Broken	278.40 FS	*278.40 FS
12	1		*COVER -RR BUMPER	Broken	514.40 FS	*514.40 FS
13	1		*LAMP ASSY -REAR FOG & R/REFL ,RH	Broken	85.60 FS	*85.60 FS
14	1		*MOULDING ASSY -RR BUMPER SIDE ,R	Broken	121.60 FS	*121.60 FS
15	1		*BRACKET -RR BPR SIDE REINF ,RH	Broken	20.80 FS	*20.80 FS
16	1		*WIRING ASSY - BUMPER EXIN	Not Necessary	180.80 FS	*- FS
17	1		*ABSORBER -REAR BUMPER ENERGY	Not Necessary	70.40 FS	*- FS
18	1		*RAIL ASSY -REAR BUMPER	Dented	232.00 FS	*232.00 FS
19	1		*GUARD -REAR WHEEL ,RIM	Not Necessary	47.20 FS	*- FS
20	1		*GARNISH ASSY -QTR SIDE, RH	Broken	73.60 FS	*73.60 FS
21	1		*BRACKET ASSY -RR BUMPER SIDE ,RH	Broken	33.60 FS	*33.60 FS
22	1		*SENSOR ASSY -ULTRASONIC BWS	Broken	181.60 FS	*181.60 FS
23	12		*REVEL -BLIND	Necessary	9.60 FS	*9.60 FS
24	3		*HOLDER -BACK WARNING SYSTEM	Necessary	2.40 FS	*2.40 FS
25	1		*TUBE ASSY -OIL COOLER	Dented	128.80 FS	*128.80 FS
26	1		*GUARD ASSY -REAR WHEEL MUD -RH	Broken	19.20 FS	*19.20 FS
27	1		*BRACKET -RR ,RH	Dented	24.00 FS	*24.00 FS
28	1		*LAMP ASSY -REAR COMBINATION ,RH	Broken	566.40 FS	*566.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	6,232.00	3,619.60
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER ,BUMPER LWR ,SUPPORT & AFFECTED AREA	New	1,200.00	400.00
2	PAINT WORK ON FRT BUMPER & BONNET	New	700.00	350.00
3	REPLACE REAR BUMPER ,END PANEL & AFFECTED AREA REPAIR ON REAR RH FENDER	New	1,600.00	800.00
4	PAINT WORK ON REAR BUMPER ,END PANEL & REAR RH FENDER	New	1,050.00	700.00
5	REMOVE & INSTALL RADIATOR ,CONDENSER FOR FACILITATE REPAIR	New	120.00	0.00
6	TO TOP UP AIRCON GAS	New	80.00	0.00
7	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	80.00
8	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	0.00
9	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	0.00
10	PERFORM RUST PREVENTION	New	80.00	40.00
11	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
12	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
13	REMOVE & REFIT REAR AIRCON BLOWER & REAR COMPARTMENT SEAT	New	400.00	400.00
14	REPAIR REAR LAMP RH	New	400.00	400.00
15	SPRAY PAINT REAR LAMP RH	New	350.00	350.00
Gross Labour Cost (\$\$)			6,450.00	3,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >