

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22002722/AVY3M4**Date:** 31/05/2022**REFERENCE**

Insured/Claimant: TEO POH CHUAN EDWIN Policy No: DMPCSNA00261722101

Date of Loss: 19/03/2022

Nature of Claim: OD

Claim No: SNM22D201906/C01/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SBV3388Y**

Make &amp; Model: AUDI RS6, 4.0 (A)

Engine No: CRD002885

Reg. Date: 18/12/2013 (Man. Year: 2013)

Chassis No: WUAZZZ4G3EN901479

Colour: Black

Odometer: 105101 km

Engine Capacity: 3993 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 295/30R21

Rear Tyre Size: 295/30R21

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre tread depth*

| <b>COST OF CLAIMS</b>               | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                               | 36,065.50         | 14,689.90         | 21,375.60         | 59.27         |
| Miscellaneous Items                 | 0.00              | 0.00              | 0.00              |               |
| Labour                              | 15,572.00         | 6,592.00          | 8,980.00          | 57.67         |
| Paintwork Labour                    | 0.00              | 0.00              | 0.00              |               |
| Towing                              | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b> | <b>51,637.50</b>  | <b>21,281.90</b>  | <b>30,355.60</b>  | <b>58.79</b>  |
| <b>- Excess (S\$)</b>               | 3,500.00          | 3,500.00          | 0.00              | 0.00          |
| <b>(S\$)</b>                        | 48,137.50         | 17,781.90         | 30,355.60         | 63.06         |
| <b>+ GST 7.00/7.00% (S\$)</b>       | 3,369.63          | 1,244.73          | 2,124.90          | 63.06         |
| <b>Nett Amount (S\$)</b>            | <b>51,507.13</b>  | <b>19,026.63</b>  | <b>32,480.50</b>  | <b>63.06</b>  |

**INSPECTION**

Date of Assignment: 24/03/2022

Date Inspected: 25/03/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | (Last Synchronised: 31 May 2022)   |  |
| <b>Parts:</b>        | N/A  | AUDI RS6 4.0 (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SBV3388Y)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                  | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT FENDER                                | Dented        | 4,192.00 FS | *4,192.00 FS |
| 2   | 1   |          | *FRONT FENDER BRACE - RH                     | Not Necessary | 107.00 FS   | *- FS        |
| 3   | 1   |          | *FRONT FENDER CLOSING ELEMENT - RH           | Not Necessary | 60.00 FS    | *- FS        |
| 4   | 1   |          | *FRONT DOOR - RH                             | Dented        | 4,760.00 FS | *4,760.00 FS |
| 5   | 1   |          | *FRONT DOOR OUTER SEAL                       | Necessary     | 256.00 FS   | *256.00 FS   |
| 6   | 1   |          | *BONDING AGENT                               | Not Necessary | 51.00 FS    | *- FS        |
| 7   | 1   |          | *CLEANING SOLUTION                           | Not Necessary | 74.00 FS    | *- FS        |
| 8   | 1   |          | *APPLICATOR                                  | Not Necessary | 8.00 FS     | *- FS        |
| 9   | 1   |          | *FRONT DOOR OUTER SEAL LOWER - RH            | Not Necessary | 256.00 FS   | *- FS        |
| 10  | 1   |          | *FRONT DOOR CATCH - RH (NPA)                 | Not Necessary | 0.00 FS     | *- FS        |
| 11  | 1   |          | *FRONT DOOR SEAL OUTER - RH LOWER            | Necessary     | 213.00 FS   | *213.00 FS   |
| 12  | 1   |          | *FRONT DOOR HINGE - RH LOWER                 | Bent          | 112.50 FS   | *112.50 FS   |
| 13  | 1   |          | *TREADED PLATE - UPPER / LOWER - LH / RH     | Lower Damaged | 35.00 FS    | *17.40 FS    |
| 14  | 1   |          | *TYRE PRESSURE DATA PLATE                    | Necessary     | 42.00 FS    | *30.00 FS    |
| 15  | 1   |          | *AB PILLAR TRIM - RH                         | Repair        | 2,857.00 FS | *- FS        |
| 16  | 2   |          | *A PILLAR END CAP - RH FRONT / REAR          | Not Necessary | 1,496.00 FS | *- FS        |
| 17  | 1   |          | *A PILLAR TRIM BRACKET - RH                  | Not Necessary | 92.00 FS    | *- FS        |
| 18  | 1   |          | *AB PILLAR ATTACHMENT PARTS                  | Necessary     | 656.00 FS   | *656.00 FS   |
| 19  | 1   |          | *DOUBLE-SIDED ADHESIVE TAPES                 | Necessary     | 55.00 FS    | *55.00 FS    |
| 20  | 1   |          | *A-PILLAR - RH                               | Repair        | 8,190.00 FS | *- FS        |
| 21  | 1   |          | *FRONT STONE GUARD FILM - RH                 | Not Necessary | 770.00 FS   | *- FS        |
| 22  | 1   |          | *FRONT DOOR LIGHT FIBRE - RH                 | Not Necessary | 2,410.00 FS | *- FS        |
| 23  | 1   |          | *REAR DOOR LIGHT FIBRE - RH                  | Not Necessary | 1,887.00 FS | *- FS        |
| 24  | 1   |          | *FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH | Not Necessary | 571.00 FS   | *- FS        |
| 25  | 1   |          | *ROOF MOLDING - RH                           | Not Necessary | 902.00 FS   | *- FS        |
| 26  | 1   |          | *DATA TAG                                    | Not Necessary | 515.00 FS   | *- FS        |
| 27  | 1   |          | *ARYLIC SEALANT                              | Not Necessary | 180.00 FS   | *- FS        |
| 28  | 1   |          | *CAVITY WAX                                  | Not Necessary | 140.00 FS   | *- FS        |
| 29  | 1   |          | *STONE CHIP                                  | Not Necessary | 180.00 FS   | *- FS        |
| 30  | 1   |          | *METAL FILLER POWDER                         | Not Necessary | 280.00 FS   | *- FS        |
| 31  | 1   |          | *SUNDRIES                                    | Necessary     | 350.00 FS   | *30.00 FS    |
| 32  | 1   |          | *RHS FRONT DOOR BOARD PANEL                  | Cracked       | 4,368.00 FS | *4,368.00 FS |

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **36,065.50**    **14,689.90**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's       | Amount          |
|---------------------------------|---|----------|------------------|-----------------|
| <b>Labour Items</b>             |   |          |                  |                 |
| 1                               | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.  | New      | 480.00           | 0.00            |
| 2                               | TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.   | New      | 1,800.00         | 0.00            |
| 3                               | TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.   | New      | 400.00           | 400.00          |
| 4                               | TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER, RHS FRONT DOOR AND RHS SILL PANEL TRIM. TO CUT OUT RHS A-PILLAR AND RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | New      | 7,200.00         | 2,800.00        |
| 5                               | TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, RHS SILL PANEL TRIM, RHS SILL PANEL, DOOR ENTRANCE AND RHS A-PILLAR.   | New      | 5,500.00         | 3,200.00        |
| 6                               | TO CARRY OUT DIAGNOSTIC CHECK.  | New      | 192.00           | 192.00          |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>15,572.00</b> | <b>6,592.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >