

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002724/ENY3Q2**Date:** 30/01/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00147682100

**Claimant Vehicle
No :** SKQ8674H**Insured
Vehicle No :** XE4170E

Date of Loss: 18/03/2022

Nature of Claim: TP

Claim
No: SNM22D201900/C02/LEWLCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKQ8674H**

Make & Model: VOLKSWAGEN JETTA, 1.4 (A)

Engine No: CAXE81341

Reg. Date: 02/01/2015 (Man. Year: 2014)

Chassis No: WVVZZZ16ZEM059492

Colour: Silver

Odometer: 58549 km

Engine Capacity: 1390 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,846.40	6,799.96	4,046.44	37.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,972.00	5,172.00	2,800.00	35.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,818.40	11,971.96	6,846.44	36.38
+ GST 8.00/8.00% (S\$)	1,505.47	957.76	547.71	36.38
Nett Amount (S\$)	20,323.87	12,929.72	7,394.15	36.38

INSPECTION

Date of Assignment: 24/03/2022

Date Inspected: 25/03/2022

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jan 2023)
Parts:	143	VOLKSWAGEN JETTA 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ8674H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	2,701.00 FS	*2,445.23 FS
2	5		*MULTI POINT SOCKET HEAD BOLT	Not Necessary	32.00 FS	*- FS
3	1		*ANTI COROSION WAX	Not Necessary	51.00 FS	*- FS
4	1		*DOOR INNER SEAL	Not Necessary	345.00 FS	*- FS
5	1		*DOOR CATCH (NPA)	Not Necessary	0.00 FS	*- FS
6	1		*FRONT DOOR HANDLE RH	Not Necessary	204.00 FS	*- FS
7	1		*FRONT DOOR HANDLE CAP RH	Not Necessary	41.00 FS	*- FS
8	1		*WINDOW SLOT SEAL OUTER RH	Not Necessary	315.00 FS	*- FS
9	1		*REAR DOOR RH	Dented	2,701.00 FS	*2,445.23 FS
10	2		*SOCKET HEAD BOLT	Not Necessary	15.00 FS	*- FS
11	4		*MULTI POINT SOCKET HEAD BOLT	Not Necessary	24.00 FS	*- FS
12	1		*ANTI COROSION WAX	Not Necessary	51.00 FS	*- FS
13	1		*DOOR INNER SEAL REAR RH	Not Necessary	345.00 FS	*- FS
14	1		*DOOR CATCH (NPA)	Not Necessary	0.00 FS	*- FS
15	1		*DOOR OUTER SEAL	Necessary	182.00 FS	*181.50 FS
16	1		*WINDOW SLOT SEAL OUTER RH	Not Necessary	315.00 FS	*- FS
17	1		*WINDOW APERTURE SEAL -BLACK	Not Necessary	174.00 FS	*- FS
18	1		*WINDOW REGULATOR RH	Not Necessary	377.00 FS	*- FS
19	1		*WINDOW REGULATOR COVER RH	Not Necessary	34.00 FS	*- FS
20	1		*WINDOW REGULATOR MOTOR RH	Not Necessary	934.00 FS	*- FS
21	1		*RHS REAR RIM RH	Cut	1,047.00 FS	*1,047.00 FS
22	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
23	1		*SUNDRIES	Necessary	300.00 FS	*22.60 FS
24	1		*FRONT DOOR LOWER SEAL -RH	Necessary	116.50 FS	*116.50 FS
25	1		*REAR DOOR BOWDEN CABLE -RH	Necessary	68.10 FS	*68.10 FS
26	1		*REAR DOOR FIXED WINDOW WITH SEAL -RH	Necessary	196.00 FS	*196.00 FS
27	2		*DOOR SOUND ABSORBER	Necessary	97.80 FS	*97.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **10,846.40** **6,799.96**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND REINSTALL REAR BUMPER	New	1,000.00	500.00
2	TO RESPRAY REAR BUMPER	New	1,000.00	500.00
3	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	700.00	700.00
4	TO DISMANTLE AND RENEW RHS FRONT DOOR AND RHS REAR DOOR .TO REPAIR RHS SILL PANEL AND RHS REAR FENDER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,800.00	1,500.00
5	TO RESPRAY RHS FRONT DOOR ,RHS REAR DOOR ,DOOR HANDES ,RHS SILL PANEL ,RHS REAR FENDER AND DOOR ENTRANCE	New	2,000.00	1,500.00
6	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,972.00	5,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >