

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22002731/UNY3Q2
Date: 19/10/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNA00094892101	
Claimant Vehicle No: SJN9531H	Insured Vehicle No: GBF2967S	
Date of Loss: 28/02/2022	Nature of Claim: TP	Claim No: SNM22D202027/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM9531H		
Make & Model:	HYUNDAI HD AVANTE, 1.6 (A)	Engine No:	G4FC9U614693
Reg. Date:	06/03/2009 (Man. Year: 2009)	Chassis No:	KMHDU41BR9U706685
Colour:	Black	Odometer:	65435 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,276.80	396.80	3,880.00	90.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,270.00	650.00	620.00	48.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,546.80	1,046.80	4,500.00	81.13
Approved Total (Overridden) (S\$)		800.00		
(S\$)	5,546.80	800.00	4,746.80	85.58
+ GST 7.00/7.00% (S\$)	388.28	56.00	332.28	85.58
Nett Amount (S\$)	5,935.08	856.00	5,079.08	85.58

INSPECTION

Date of Assignment:	27/03/2022		
Date Inspected:	19/09/2022	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2022)
Parts: 143	HYUNDAI HD AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJN9531H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER W/SIDE HOLDER (11 PCS)	Dented / Deformed (1 PCS ONLY)	4,917.00 FL	*447.00 FL	
2	1		*SET REAR BUMPER CLIPS	Necessary	49.00 FL	*49.00 FL	
3	1		*REAR BUMPER FOAM	Not Necessary	110.00 FL	*- FL	
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	270.00 FL	*- FL	
					Sub Total (\$\$)	5,346.00	496.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,069.20	99.20
					Total Parts (\$\$)	4,276.80	396.80

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PARTS	New	600.00	200.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	500.00	400.00
3	TO CHECK WIRING }	New	50.00	50.00
4	TO TRANSFER REAR BUMPER SENSOR }	New	120.00	0.00
			Gross Labour Cost (\$\$)	650.00
			1,270.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >