

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG22002737/EVY3N2**Date:** 17/04/2022**REFERENCE**

Insured/Claimant:	LEONG KIN YIP (LIANG JIANYE)	Policy No:	1800041040
Date of Loss:	23/03/2022	Nature of Claim:	OD Claim No: 7972905383SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SLZ3378L	Engine No:	3A92UGS5752
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AJH001872
Reg. Date:	18/04/2018 (Man. Year: 2018)	Odometer:	56859 km
Colour:	White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$53,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,818.00	3,135.24	682.76	17.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,120.00	2,305.00	815.00	26.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,938.00</b>	<b>5,440.24</b>	<b>1,497.76</b>	<b>21.59</b>
<b>- Excess (S\$)</b>	300.00	300.00	0.00	0.00
<b>(S\$)</b>	6,638.00	5,140.24	1,497.76	22.56
<b>+ GST 7.00/7.00% (S\$)</b>	464.66	359.82	104.84	22.56
<b>Nett Amount (S\$)</b>	<b>7,102.66</b>	<b>5,500.06</b>	<b>1,602.60</b>	<b>22.56</b>

**INSPECTION**

Date of Assignment:	24/03/2022	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Date Inspected:	24/03/2022 Inspected At:	
Estimated Period of Repair:	4.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*UNPAINTED BODYKITS	Broken	1,643.00 FS	*1,643.00 FS
2	1		*FACE,FR BUMPER	Broken	706.00 F	*706.00 FL
3	1		*BRACKET,FR BUMPER,RH	Broken	13.00 F	*13.00 FL
4	1		*AIR DAM,SIDE,FR RH	Not Necessary	18.00 F	*- FL
5	1		*GARNISH,FR BUMPER,RH	Not Necessary	127.00 F	*- FL
6	1		*HEADLAMP ASSY,RH	Broken	663.00 F	*663.00 FL
7	1		*FENDER,FR RH	Dented	500.00 F	*500.00 FL
8	1		*SHIELD,FR WHEELHOUSE,RH	Not Necessary	98.00 F	*- FL
9	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
10	1		*Rivet, Fr bumper (6 pcs) (Supplementary)	Necessary	30.00 F	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,818.00	3,575.00
- List Item Discount on L Items 0.00/23.00% (S\$)	0.00	439.76
Total Parts (S\$)	3,818.00	3,135.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	*OD/TP Case (Insurer)	-	0.00
<b>Sub Total (\$\$)</b>			<b>0.00</b>	<b>0.00</b>

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW FRT AIRDAM,FRT BUMPER,FRT FENDER RH,REPAIR BONNET	New	1,350.00	675.00
2	SPRAY PAINT FOR FRT BUMPER,AIRDAM,FRT FENDER RH,BONNET	New	1,400.00	1,400.00
3	REMOVE & INSTALL FRT AIRDAM	New	100.00	80.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
6	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,120.00</b>	<b>2,305.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >