

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG22002739/EVY3E2

Date: 09/05/2022

REFERENCE

Insured/Claimant:	PEH KIM HUAT	Policy No:	1900000814		
Date of Loss:	23/03/2022	Nature of Claim:	OD	Claim No:	8615775096SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG9788K	Engine No:	G4FGJH713520
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5024544
Reg. Date:	08/01/2019 (Man. Year: 2018)	Odometer:	90580 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$76,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,424.00	3,112.40	311.60	9.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,500.00	800.00	34.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,724.00	4,612.40	1,111.60	19.42
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,124.00	4,012.40	1,111.60	21.69
+ GST 7.00/7.00% (S\$)	358.68	280.87	77.81	21.69
Nett Amount (S\$)	5,482.68	4,293.27	1,189.41	21.69

INSPECTION

Date of Assignment:	24/03/2022	
Date Inspected:	25/03/2022 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*LAMP ASSY-HEAD, RH	Cut	1,247.00 FL	*1,247.00 FL
4	1		*COVER-FR BUMPER	Dented	633.00 FL	*633.00 FL
5	1		*GRILLE-FRONT BUMPER	Cut	262.00 FL	*262.00 FL
6	1		*MOULDING-FRONT BUMPER, RH	Not Necessary	36.00 FL	*- FL
7	1		*LAMP ASSY-SIDE REPEATER, RH	Not Necessary	164.00 FL	*- FL
8	1		*GRILLE ASSY-RADIATOR	Cut	328.00 FL	*328.00 FL
9	1		*GARNISH-RADIATOR GRILLE	Not Necessary	38.00 FL	*- FL
10	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
11	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
12	1		*BEAM COMPLETE-FR BUMPER	Dented	497.00 FL	*497.00 FL
13	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
14	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
15	10		*CLIPS (Supplementary)	Necessary	10.00 FL	*10.00 FL
16	1		*COOLANT (4L) (Supplementary)	Necessary	26.00 FL	*26.00 FL
17	1		*CAP-FRONT HOOK (Supplementary)	Crushed	9.00 FL	*9.00 FL
					Sub Total (\$\$)	4,255.00 3,873.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	831.00 760.60
					Total Parts (\$\$)	3,424.00 3,112.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER, SUPPORT & AFFECTED AREA	New	1,200.00	400.00
2	PAINT WORK ON FRT BUMPER PANEL	New	350.00	350.00
3	TO TOP UP AIRCON GAS	New	80.00	80.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
6	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
7	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	400.00	400.00
Gross Labour Cost (\$\$)			2,300.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >