

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002740/BVY3N2**Date:** 19/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00138992101

Claimant Vehicle No : GBL1268B**Insured Vehicle No :** QX1589J

Date of Loss: 21/03/2022

Nature of Claim: TP

Claim No: SNM22D201968/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBL1268B**

Make & Model: KIA K2500 6M/T, 2.5 D (M)

Engine No: D4CBM204535

Reg. Date: 24/03/2021 (Man. Year: 2020)

Chassis No: KNCSJX76LM7517885

Colour: White

Odometer: 17866 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Rear Tyre Size: 145R13C

Front Left Side: Kumho 5 mm

Rear Left Side: Kumho 5 mm

Front Right Side: Kumho 5 mm

Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,773.73	5,662.83	5,110.90	47.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	1,460.00	2,470.00	62.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,703.73	7,122.83	7,580.90	51.56
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	14,703.73	5,700.00	9,003.73	61.23
+ GST 7.00/7.00% (S\$)	1,029.26	399.00	630.26	61.23
Nett Amount (S\$)	15,732.99	6,099.00	9,633.99	61.23

INSPECTION

Date of Assignment: 04/05/2022

Date Inspected: 25/03/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 May 2022)	
Parts:	N/A	KIA K2500 6M/T 2.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL1268B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,284.35 FL	*1,050.00 FL
2	1		*TAILGATE RH HINGE	Not Damaged	119.00 FL	*- FL
3	1		*TAILGATE CENTRE HINGE	Necessary	119.00 FL	*78.50 FL
4	1		*TAILGATE LH HINGE	Not Damaged	119.00 FL	*- FL
5	1		*TAILGATE RH FLIP LOCK	Bent	123.00 FL	*68.70 FL
6	1		*TAILGATE LH FLIP LOCK	Bent	123.00 FL	*68.70 FL
7	1		*TAILGATE LOWER PANEL	Bent	458.80 FL	*458.80 FL
8	1		*RH TAILLAMP ASSY	Cut	155.00 FL	*155.00 FL
9	1		*RH TAILLAMP PANEL	Not Damaged	358.00 FL	*- FL
10	1		*LH TAILLAMP ASSY	Cut	155.00 FL	*155.00 FL
11	1		*LH TAILLAMP PANEL	Not Damaged	358.00 FL	*- FL
12	1		*REAR NUMBER PLATE LAMP	Broken	138.00 FL	*124.00 FL
13	1		*SPARE TYRE CARRIAGE	Not Damaged	328.00 FL	*- FL
14	1		*RH SIDE GATE	Dented	1,308.00 FL	*1,200.00 FL
15	1		*LH SIDE GATE	Dented	1,308.00 FL	*1,200.00 FL
16	1		*TAILGATE INNER ALUMINIUM PANEL	Dented	750.00 FS	*500.00 FS
17	1		*SET TAILGATE INNER ALUMINIUM PANEL RIVETS	Necessary	80.00 FS	*30.00 FS
18	1		*TAILGATE 70KM/H STICKER	Necessary	50.00 FS	*20.00 FS
19	1		*TAILGATE 13 PAX STICKER	Necessary	50.00 FS	*20.00 FS
20	1		*TAILGATE ADVERTISEMENT STICKER	Necessary	480.00 FS	*250.00 FS
21	1		*TAILGATE C&C EMBLEM	Necessary	85.00 FS	*50.00 FS
22	1		*REAR NUMBER PLATE	Bent	70.00 FS	*40.00 FS
23	1		*SET REAR REVERSE SENSOR	Short Circuit	280.00 FS	*200.00 FS
24	1		*REAR UNDERRUN BUMPER	Bent	1,200.00 FS	*450.00 FS
25	1		*RH SIDE GATE INNER ALUMINIUM PANEL	Not Damaged	880.00 FS	*- FS
26	1		*SET RH SIDE GATE INNER ALUMINIUM PANEL RIVETS	Not Damaged	80.00 FS	*- FS
27	1		*LH SIDE GATE INNER ALUMINIUM PANEL	Not Damaged	880.00 FS	*- FS
28	1		*SET LH SIDE GATE INNER ALUMINIUM PANEL RIVETS	Not Damaged	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,419.15	6,118.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	645.42	455.87
Total Parts (\$\$)	10,773.73	5,662.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR SUPPLEMENTARY	New	600.00	0.00
2	SPRAY PAINTING FOR SUPPLEMENTARY	New	600.00	0.00
3	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,200.00	800.00
4	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	600.00
5	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	100.00	0.00
6	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	0.00
7	REMOVE AND REPLACE REAR REVERSE SENSORS TO ASSIST REPAIR	New	150.00	60.00
Gross Labour Cost (\$\$)			3,930.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >