

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22002741/KPA3Q2**Date:** 15/06/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MFL0000974
Claimant Vehicle No :	SKP9838B	Insured Vehicle No :	SLJ7189Z
Date of Loss:	23/03/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0001461

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP9838B	Engine No:	591556333FC
Make & Model:	JAGUAR XF, 3.0 V6 LUXURY (A)	Chassis No:	SAJAC05D8BFR97368
Reg. Date:	17/12/2010 (Man. Year: 2010)	Odometer:	103482 km
Colour:	Metallic Beige		
Engine Capacity:	2967 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45Z R18	Rear Tyre Size:	245/45Z R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	59,628.70	26,583.35	33,045.35	55.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,530.00	3,480.00	5,050.00	59.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	68,158.70	30,063.35	38,095.35	55.89
Approved Total (Overridden) (\$\$)		23,350.00		
(\$\$)	68,158.70	23,350.00	44,808.70	65.74
+ GST 7.00/7.00% (\$\$)	4,771.11	1,634.50	3,136.61	65.74
Nett Amount (\$\$)	72,929.81	24,984.50	47,945.31	65.74
+ Loss of Use (13.0 x S\$200.00/day) (\$\$)		2,600.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		27,591.95		

INSPECTION

Date of Assignment:	24/03/2022	
Date Inspected:	28/03/2022	Inspected At: MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	9.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2022)
Parts: 143	JAGUAR XF 3.0 V6 LUXURY (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKP9838B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Serviceable	3,515.00 FL	*- FL
2	1		*FRONT WINDSCREEN MOULDING	Necessary	279.00 FL	*279.00 FL
3	1		*ROOF LINING	Deformed	3,856.00 FL	*2,910.00 FL
4	1		*AIRBAG ROOF RH	Burst	1,862.00 FL	*1,862.00 FL
5	1		*AIRBAG DRIVER SEAT	Burst	1,672.00 FL	*1,672.00 FL
6	1		*AIRBAG CINTROL UNIT	Necessary	1,720.00 FL	*1,720.00 FL
7	1		*SAFETY BELT DRIVER	Serviceable	914.00 FL	*- FL
8	1		*SAFETY BELT BUCKLE DRIVER	Serviceable	787.00 FL	*- FL
9	1		*SAFETY BELT PASSENGER	Serviceable	914.00 FL	*- FL
10	1		*SAFETY BELT BUCKLE PASSENGER	Serviceable	787.00 FL	*- FL
11	1		*DRIVER SEAT UPHOLSTERY	Torn	2,850.00 FL	*2,850.00 FL
12	1		*FRONT DOOR RH	Bent	4,865.00 FL	*3,090.60 FL
13	1		*FRONT DOOR FRAME CHROME UPPER RH	Serviceable	965.00 FL	*- FL
14	1		*FRONT DOOR FRAME CHROME LOWER RH	Serviceable	642.00 FL	*- FL
15	1		*FRONT DOOR PILLAR GARNISH RH	Serviceable	341.00 FL	*- FL
16	1		*FRONT DOOR WEATHERSTRIP RH (50%)	Necessary	261.00 FS	*145.00 FS
17	1		*FRONT DOOR HINGE RH UPPER RH	Repair	174.00 FL	*- FL
18	1		*FRONT DOOR HINGE RH LOWER RH	Repair	174.00 FL	*- FL
19	1		*FRONT DOOR OUTER HANDLE RH	Serviceable	718.00 FL	*- FL
20	1		*FRONT DOOR POWER WINDOW LIFTER RH	Jammed	794.00 FL	*794.00 FL
21	1		*FRONT DOOR INNER BOARD RH	Serviceable	3,145.00 FL	*- FL
22	1		*FRONT DOOR WINDOW GLASS RH	Serviceable	684.00 FL	*- FL
23	1		*REAR DOR RH	Dented / Warped	4,865.00 FL	*3,079.90 FL
24	1		*REAR DOOR FRAME CHROME UPPER RH	Serviceable	965.00 FL	*- FL
25	1		*REAR DOOR FRAME CHROME LOWER RH	Serviceable	642.00 FL	*- FL
26	1		*REAR DOOR PILLAR GARNISH RH	Serviceable	341.00 FL	*- FL
27	1		*REAR DOOR WEATHERSTRIP RH (50%)	Cut	256.50 FS	*142.50 FS
28	1		*REAR DOOR HINGE RH UPPER RH	Repair	174.00 FL	*- FL
29	1		*REAR DOOR HINGE RH LOWER RH	Repair	174.00 FL	*- FL
30	1		*REAR DOOR OUTER HANDLE RH	Serviceable	718.00 FL	*- FL
31	1		*REAR DOOR POWER WINDOW LIFTER RH	Serviceable	894.00 FL	*- FL
32	1		*REAR DOOR INNER BOARD RH	Serviceable	3,145.00 FL	*- FL
33	1		*REAR FENDER RH	Repair	6,852.00 FL	*- FL
34	1		*SIDE SKIRT RH	Mtg Cracked	1,420.00 FL	*1,420.00 FL
35	1		*REAR WINDSCREEN	Serviceable	2,850.00 FL	*- FL
36	1		*REAR WINDSCREEN MOULDING	Not Necessary	298.00 FL	*- FL
37	1		*REAR DRIVE SHAFT RH	Bent	2,470.00 FL	*2,470.00 FL
38	1		*REAR UPPER ARM RH	Distorted	537.00 FL	*537.00 FL
39	1		*REAR LOWER ARM R H	Bent	689.00 FL	*671.00 FL
40	1		*REAR SHOCK ABSORBER RH	Bent	575.00 FL	*489.00 FL
41	1		*REAR KNUCKLE ARM RH	Dented	1,205.00 FL	*1,196.00 FL
42	1		*REAR WHEEL HUB +BEARING RH	Bent / Necessary	684.00 FL	*541.00 FL
43	1		*REAR TIE ROD END RH	Bent	589.00 FL	*382.00 FL
44	1		*BODY SEALANT	Not Necessary	80.00 FS	*- FS
45	1		*WINDSCREEN SEALANT FRONT	Necessary	80.00 FS	*40.00 FS
46	1		*WINDSCREEN SEALANT REAR	Not Necessary	80.00 FS	*- FS
47	1		*REAR SPORTS RIM RH	Dented	1,485.00 FS	*1,220.00 FS
48	1		*FRONT DOOR INNER SPONGE RH	Cracked	248.00 FL	*248.00 FL
49	1		*FRONT DOR INNER HANDLE BRACKET HOLDER RH	Cracked	480.00 FL	*480.00 FL

Report was unsubmitted during this print-out.

F=Franchise part. S=SpcNett. L=ListItemDisc.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=1077679&extid=382109&CFID=10735... 3/4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS	New	2,500.00	1,000.00
2	TO REMOVE & REPLACE FRONT WINDSCREEN	New	150.00	120.00
3	TO REMOVE & REPLACE REAR WINDSCREEN	New	150.00	0.00
4	TO DISMANTLE & TRANSFER FRONT DOOR FITTINGS & MECHANISM TO NEW DOOR	New	140.00	80.00
5	TO DISMANTLE & TRANSFER REAR DOOR FITTINGS & MECHANISM TO NEW DOOR	New	140.00	80.00
6	TO REMOVE & INSTALL REAR UPHOLSTERY TO FACILITATE REPLACE REAR FENDER RH	New	150.00	0.00
7	TO DISMANTLE AND REPLACE REAR RH UNDERCARRIAGE	New	350.00	200.00
8	TO REMOVE & REPLACE ROOF LINING	New	400.00	150.00
9	TO REMOVE AND REFIT FUEL TANK FIXTURE TO FACILITATE REPAIRS	New	140.00	0.00
10	TO RE-PROGRAM SRS AIR BAG CONTROL UNIT }	New	450.00	300.00
11	TO REMOVE & REPLACE SRS AIR BAG CONTROL UNIT }	New	250.00	0.00
12	TO REMOVE & REPLACE SAFETY BELT DRIVER	New	200.00	0.00
13	TO REMOVE & REPLACE SAFETY BELT BUCKLE DRIVER	New	200.00	0.00
14	TO REMOVE & REPLACE SAFETY BELT PASSENGER	New	200.00	0.00
15	TO REMOVE & REPLACE SAFETY BELT PASSENGER	New	200.00	0.00
16	TO REMOVE & REPLACE AIRBAG DRIVER SEAT }	New	400.00	180.00
17	TO REMOVE & REPLACE DRIVER SEAT UPHOLSTERY }	New	300.00	0.00
18	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	New	150.00	60.00
19	TO RESET ENGINE WARNING LIGHT (ABS ,SRS ,ECU MEMORY & ETC)	New	250.00	200.00
20	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	50.00	30.00
21	TO APPLY ANTI RUST COATING	New	80.00	60.00
22	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,600.00	1,000.00
23	TO REMOVE ,RENEW & FRT REAR RH TYRE	New	80.00	20.00
Gross Labour Cost (\$\$)			8,530.00	3,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >