

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22002747/APA3Q2**Date:** 11/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100221886-11
<b>Claimant Vehicle No :</b>	SMJ3816L	<b>Insured Vehicle No :</b>	SJR8036G
Date of Loss:	24/03/2022	Nature of Claim:	TP
		Claim No:	2531668383SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMJ3816L</b>		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK074456
Reg. Date:	28/02/2019 (Man. Year: 2018)	Chassis No:	WAUZZZF55KA015107
Colour:	Red	Odometer:	41254 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,538.00	3,784.80	6,753.20	64.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,152.00	2,152.00	3,000.00	58.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>15,690.00</b>	<b>5,936.80</b>	<b>9,753.20</b>	<b>62.16</b>
<b>+ GST 7.00/7.00% (S\$)</b>	1,098.30	415.58	682.72	62.16
<b>Nett Amount (S\$)</b>	<b>16,788.30</b>	<b>6,352.38</b>	<b>10,435.92</b>	<b>62.16</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>6,854.38</b>		

INSPECTION

Date of Assignment:	06/04/2022		
Date Inspected:	06/04/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	3,011.00 FS	*2,408.80 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	172.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	249.00 FS	*198.80 FS
4	1		*REAR BUMPER CHROME TRIM	Cracked	1,139.00 FS	*911.20 FS
5	1		*REAR LIGHT REFLECTOR-LH	Cut	46.00 FS	*36.48 FS
6	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,131.00 FS	*- FS
7	2		*REAR BUMPER SEAL	Not Necessary	32.00 FS	*- FS
8	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	98.00 FS	*- FS
9	2		*REAR BUMPER GUIDE SECTION UPPER-LH/RH	Not Necessary	52.00 FS	*- FS
10	2		*REAR PARKING AID SENSOR-INNER/OUTER	Not Necessary	530.00 FS	*- FS
11	1		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
12	1		*TAIL LIGHT	Not Necessary	1,269.00 FS	*- FS
13	1		*TAIL LIGHT TRIM-LH	Not Necessary	34.00 FS	*- FS
14	1		*TAIL LIGHT INNER-LH	Not Necessary	1,135.00 FS	*- FS
15	1		*TAIL LIGHT TRIM INNER-LH	Not Necessary	34.00 FS	*- FS
16	1		*REAR PACKING ADHESIVE	Necessary	21.00 FS	*16.72 FS
17	1		*AUDI EMBLEM	Necessary	163.00 FS	*130.00 FS
18	1		*A5 EMBLEM	Necessary	104.00 FS	*82.80 FS
19	1		*BOOT LID CONTROL UNIT	Not Necessary	454.00 FS	*- FS
20	1		*AERIAL FOR KESSY	Not Necessary	120.00 FS	*- FS
21	1		*AERIAL RETAINER-LH	Not Necessary	29.00 FS	*- FS
22	1		*TELEPHONE AERIAL	Not Necessary	192.00 FS	*- FS
23	1		*EXHAUST TAILPIPE-LH	Not Necessary	153.00 FS	*- FS
24	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
25	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
					<b>Total Parts (S\$)</b>	<b>10,538.00</b>
						<b>3,784.80</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND RENEW REAR PARKING AIR AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR REAR LID AND LHS TAILLAMP PANEL.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY REAR BUMPER,REAR LID AND LHS TAILLAMP PANEL	New	3,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,152.00</b>	<b>2,152.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >