

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 8 working days to complete
5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SMJ4042X

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Rear bumper ✓	bend/deformed	\$ 1,950.00	\$ 1512 1,950.00
2 pcs	Rear bumper side retainer X SVC	bent	\$ 200.00	\$ 200.00
2 pcs	Rear bumper side attachment X SVC	bent	\$ 120.00	\$ 120.00
10 pcs	Rear bumper clips ✓	necessary	\$ 100.00	\$ 40 100.00
1 pc	Rear bumper reinforcement ✓	bent	\$ 562.80	\$ 381 562.80
1 pc	Rear end panel	bent/distorted - repair	\$ 798.00	\$ -
1 pc	Rear end panel top garnish ✓	bent/distorted	\$ 425.00	\$ 115.2 425.00
Parts Sub-Total			\$ 4,155.80	\$ 2048.2 3,357.80
Discount 10.00%			\$ 415.58	\$ 335.78
			\$ 3,740.22	\$ 1843.38 3,022.02

Vehicle Number : SMJ4042X

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>Special Nett Items</i>				
1 set	Reverse sensor X SVC	electronically shocked	\$ 280.00	\$ 250.00
Special Nett Sub-Total			\$ 280.00	\$ 250.00
Spare Parts Total			\$ 4,020.22	\$ 3,272.02

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare Parts Total c/f	\$ 4,020.22	\$ 3,272.02
1	To tuff coat affected areas	\$ 180.00	\$ 150.00 X
2	To remove and replace interior upholstery	\$ 180.00	\$ 150.00 60
3	To remove and replace reverse sensor	\$ 180.00	\$ 150.00 40
4	To respray affected areas	\$ 1,600.00	\$ 1,400.00 400
5	To renew damaged parts, straighten and repair rear chassis member, rear fender inner panel , rear door and aligned all parts.	\$ 1,800.00	\$ 1,600.00 400
6	To do up paint protection coating	\$ 1,200.00	\$ 1,200.00 X
	Total	\$ 7,960.22	\$ 6,722.02

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 5,500.00
 2743.38
 -20%: 2200
 4 Days



Fong Kok Heng
 Qualified Appraiser

