



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS3/ASM21010293/Gcy3e2-1 Date: 16/12/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SHB 2154X	Veh. Inspected	PC 3923L
	Policy No.	VFX/P2419140	Coverage (\$)	0.00
	Claim No.	S1M03JED	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	24/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE COMMUTER	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	KDH2230023665	Colour	WHITE
	Odometer	453956 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	MICHELIN	6 mm
	L/H Front Tyre	195 R15	MICHELIN	6 mm
	R/H Rear Tyre	195 R15	MICHELIN	6 mm
	L/H Rear Tyre	195 R15	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	05/10/2021	Inspection Date	31/08/2022
	Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	