

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22002748/EVCE2**Date:** 03/10/2022**REFERENCE**

Insured/Claimant:	EDWARD BIN CHUNG YIU	Policy No:	1800145627-03	
Date of Loss:	22/03/2022	Nature of Claim:	OD	Claim No: 6947090364SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGJ6328E		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK073207
Reg. Date:	12/12/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF57KA009714
Colour:	Grey	Odometer:	46373 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$151,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,626.28	12,902.42	21,723.86	62.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,152.00	6,132.00	6,020.00	49.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,778.28	19,034.42	27,743.86	59.31
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	45,178.28	17,434.42	27,743.86	61.41
+ GST 7.00/7.00% (S\$)	3,162.48	1,220.41	1,942.07	61.41
Nett Amount (S\$)	48,340.76	18,654.83	29,685.93	61.41

INSPECTION

Date of Assignment:	25/03/2022	
Date Inspected:	24/03/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	9.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	3,127.00 FS	*- FS
2	2		*FRONT BUMPER AIR GUIDE-LH/RH	Not Necessary	72.00 FS	*- FS
3	2		*FRONT BUMPER AIR GUIDE SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	778.00 FS	*- FS
5	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	41.00 FS	*- FS
6	1		*FRONT FENDER-LH	Dented	1,189.00 FS	*951.20 FS
7	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
8	1		*FRONT FENDER CLOSING ELEMENT-LH	Necessary	83.00 FS	*65.84 FS
9	1		*FRONT FENDER BRACKET-LH	Broken	41.00 FS	*32.72 FS
10	1		*FRONT FENDER POP RIVET (5 Pcs)	Necessary	19.00 FS	*15.20 FS
11	1		*FRONT FENDER BRACKET END-LH	Not Necessary	65.00 FS	*- FS
12	1		*FRONT FENDER BRACKET CENTER-LH	Not Necessary	40.00 FS	*- FS
13	1		*FRONT FENDER BRACE-LH	Not Necessary	132.00 FS	*- FS
14	1		*FRONT FENDER BRACKET CENTER-LH	Not Necessary	55.00 FS	*- FS
15	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	299.00 FS	*- FS
16	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	176.00 FS	*- FS
17	1		*FRONT WHEEL HOUSING LINER TRIM BRACKET-LH	Not Necessary	27.00 FS	*- FS
18	1		*FRONT STONE CHIP GUARD-LH	Not Necessary	57.00 FS	*- FS
19	1		*FRONT FENDER LEDGE COVER LONG-LH	Broken	40.00 FS	*31.44 FS
20	1		*FRONT FENDER LEDGE COVER SHORT-LH	Broken	18.00 FS	*13.92 FS
21	1		*FRONT FENDER LEDGE COVER INNER-LH	Crushed	81.00 FS	*64.24 FS
22	1		*FRONT PLENUM CHAMER	Not Necessary	108.00 FS	*- FS
23	1		*FRONT FENDER TRIM-LH	Necessary	205.00 FS	*164.00 FS
24	1		*BONNET	Dented	3,491.00 FS	*2,792.80 FS
25	1		*BONNET ATTACHMENT PARTS	Not Necessary	128.00 FS	*- FS
26	2		*BONNET HINGE-LH/RH	Not Necessary	932.00 FS	*- FS
27	3		*BONNET IMPACT PROTECTION-CENTER/LH/RH	Necessary	93.00 FS	*73.20 FS
28	1		*BONNET SOUND ABSORBER	Not Necessary	382.00 FS	*- FS
29	2		*BONNET STRIKER-LH/RH	Not Necessary	112.00 FS	*- FS
30	2		*BONNET LOCK	Not Necessary	455.00 FS	*- FS
31	1		*BONNET VOWDEN CABLE-CENTER	Not Necessary	64.00 FS	*- FS
32	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
33	1		*HEADLIGHT-LH	Not Necessary	8,416.00 FS	*- FS
34	1		*FRONT DOOR-LH	Dented	3,977.00 FS	*3,181.60 FS
35	1		*FRONT DOOR OUTER SEAL-LH	Necessary	247.00 FS	*197.20 FS
36	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
37	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
38	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
39	1		*FRONT DOOR CATCH-RH	Not Necessary	0.00 FS	*- FS
40	1		*WING MIRROR MOUNTING-LH	Missing	1,201.00 FS	*960.80 FS
41	1		*WING MIRROR GLASS-LH	Broken	1,298.00 FS	*1,038.40 FS
42	1		*WING MIRROR CAP	Missing	308.00 FS	*246.00 FS
43	1		*FRONT DOOR WINDOW APERTURE SEAL-LH INNER	Not Necessary	453.00 FS	*- FS
44	1		*FRONT DOOR TRIM COVER-LH	Cut	51.00 FS	*40.40 FS
45	1		*FRONT DOOR WINDOW SLOT SEAL TRIM STRIP-LH	Not Necessary	446.00 FS	*- FS
46	1		*ROOF MOLDING-LH	Cut	706.00 FS	*564.80 FS
47	1		*FRONT DOOR EDGE PROTECTION-LH	Not Necessary	172.00 FS	*- FS
48	1		*FRONT DOOR WINDOW REGULATOR-LH	Not Necessary	392.00 FS	*- FS
49	1		*FRONT DOOR WINDOW-LH	Not Necessary	322.00 FS	*- FS
50	1		*FRONT DOOR TRIM-LH	Necessary	171.00 FS	*136.40 FS
51	1		*WINDSCREEN WATER DEFLECTOR STRIP	Not Necessary	75.00 FS	*- FS
52	1		*FRONT BUMPER FOAM FILLER PIECE-LH	Not Necessary	21.00 FS	*- FS
53	1		*ALUMINIUM RIM	Cut	2,559.00 FS	*2,047.20 FS
54	1		*RUBBER VALVE (4 Pcs)	Necessary (1 Pc only)	15.00 FS	*3.70 FS

Report was unsubmitted during this print-out.

10/3/22, 2:12 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*SUNDRIES	Necessary	350.00 FS	*119.04 FS
56	1		*FRONT BUMPER TOP COVER (Supplementary)	Broken	143.00 FS	*114.00 FS
57	1		*SIGN CAUTION STICKER (Supplementary)	Necessary	16.00 FS	*12.40 FS
58	1		*STICKER FOR AIR CONDITIONER (Supplementary)	Necessary	9.00 FS	*6.64 FS
59	2		*RADIATOR AIR GUID-UPPER LH/RH (Supplementary)	Broken	29.28 FS	*29.28 FS
60	1		*FRONT DOOR SEAL INNER	Not Necessary	657.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	34,626.28 12,902.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO REMOVE AND TRANSFER LHS FRONT DOOR SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	400.00	280.00
4	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR WINDOW GLASS	New	400.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET,LHS FRONT FENDER,LHS FRONT DOOR AND LHS HEADLIGHT.TO REPAIR LHS UPPER A-PILLAR.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,500.00	2,000.00
6	TO RESPRAY FRONT BUMPER,BONNET,HINGES,LHS FRONT FENDER,LHS FRONT DOOR,LHS WING MIRROR COVER,DOOR HANDLE AND LHS UPPER A-PILLAR	New	5,500.00	2,900.00
7	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			12,152.00	6,132.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >