

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22002750/Eqy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	05/05/2022		
	ATTN: LOH CYNTH	AIF		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 7108L	Veh. Inspected	ł	JTR 6846	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M03VE5	Excess (\$)		0.00	
	Assign From	LOH CYNTHIA	Assign Date		25/03/2022	
2.	. Vehicle Particulars & Condition					
	Make & Model	YAMAHA R25	c.c		250	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	PMYRG1520K0001943	Colour		RED	
	Odometer	30260 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	110/70-17	DUNLOP		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70-17	DUNLOP		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
5.	5. General Information					
	Accident Date	08/03/2022	Inspect Date /	Time	25/03/2022 (03:53 PM)	
	Survey held at	urvey held at YONG SENG HENG MOTOR SERVICES				
		NO. 5 SOON LEE STREET #01-12 PIONEER POINT SINGAPORE 627607				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b. Estimate Days of Repair						
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM22002750/Eqy3e2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser