



Vehicle Inspection Report

To: Faizal Sallim Bin Ahmad Date of report: 01.12.2021
C/o: No.10 Kaki Bukit Road 2 #01-24, First East Centre Date of request: 08.11.2021
Singapore 417868 Date of inspection: 08.11.2021
Date of accident: 06.09.2021
Report No: AAS/2021/262 Claim type: Third Party Claim

Particulars of affected vehicle:

Registration no:	FBR4926J	Odometer:	Not Working
Make/Model:	Yamaha R15 ABS (Motorcycle)	Engine Capacity:	155 cc
Year of registration:	2020	Engine no:	G3N4E0025892
Colour:	Black	Chassis no:	ME1RG6713L0022186

Condition of tires:

Front: 5mm
Make: MRF
Rear: 5mm
Make: MRF

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

The Assignment

The inspection was conducted at M/s. Motoplex Pte Ltd
No.10 Kaki Bukit Road 2 #01-24, First East Centre
Singapore 417868

(Subsequent inspection was conducted)

Assessment

Repairer's estimate:	\$ 12,238.10
Revised estimate:	\$ 9,333.80
Recommended reserve:	\$ 7,450.00 (Lump sum)

Estimated normal duration of repairs : 4 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: FBR4926J

Report No: AAS/2021/262

W/O PREJUDICE

Point of impact

At the front portion.

General description of damages

The front fender, front forks, front fork under bracket, headlight, headlight cowling, side cowlings, footrest, handlebars, exhaust muffler, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Motoplex Pte Ltd as per schedule attached have been revised and scrutinized. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$9,333.80

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$7,450.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 4 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 207 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



Vehicle No: FBR4926J

Report No: AAS/2021/262

Appraisal Schedule

S/N	Parts Description	Qty	Condition		Repairer's Est	Revised Est
1	Front fender		Cracked		\$ 160.00 110-	\$ 160.00
2	Wheel rim front	1	Refit		\$ 1,050.00	-
3	Wheel bearing	2	Refit	\$ 60.00	\$ 120.00	-
4	Wheel axle	1	Refit		\$ 70.00	-
5	Front fork LH/RH	2	Grazed/Bent	\$ 500 850.00	\$ 1,700.00 1000-	1,700.00
6	Front fork under comp	1	Distorted		\$ 620.00 250-	\$ 620.00
7	Cone bearing	1	Damaged		\$ 105.00 80-	\$ 105.00
8	Headlight	1	Grazed/Cut		\$ 985.00 180-	\$ 985.00
9	Headlight cowling	1	Grazed/Cut		\$ 275.00 180-	\$ 275.00
10	Headlight lip LH	1	Grazed/Cut		\$ 65.00	\$ 65.00 -
11	Front cowling	1	Grazed/Cut		\$ 130.00	\$ 130.00 -
12	Visor	1	Refit		\$ 160.00	-
13	Flasher light front LH/RH	2	Broken/Missing	\$ 75 90.00	\$ 180.00 150-	\$ 180.00
14	Panel console LH/RH	2	Refit	\$ 35.00	\$ 70.00	-
15	Side panel LH/RH	2	Grazed/Cut	180 \$ 375.00	\$ 750.00 360-	\$ 750.00
16	Side panel inner LH/RH	2 1	Grazed/Cut	80 \$ 140.00	\$ 280.00 80-	\$ 140.00
17	Lower panel LH/RH	2	Grazed/Cut	140 \$ 210.00	\$ 420.00 280-	\$ 420.00
18	Sticker LH/RH	2	Necessary	\$ 30.00	\$ 60.00	\$ 60.00 -
19	Handlebar LH/RH	2	Bent	\$ 170.00	\$ 340.00	\$ 340.00 -
20	Crown handle	1	Refit		\$ 320.00	-
21	Fuel tank cover LH/RH	2 1	LH Grazed	\$ 150.00	\$ 300.00	\$ 150.00 -
22	Emblem LH/RH	2 1	LH Necessary	\$ 25.00	\$ 50.00	\$ 25.00 -
23	Gear shift pedal	1	Bent		\$ 95.00	\$ 95.00 -
24	Footrest front LH/RH	2	Grazed	\$ 65.00	\$ 130.00	\$ 130.00 -
25	Footrest support LH/RH	2	Distorted	\$ 190.00	\$ 380.00 nn	\$ 380.00 X
26	Footrest rear LH/RH	2	LH Grazed	\$ 52.00	\$ 104.00	\$ 52.00 -
27	Footrest bracket LH/RH	2	LH Grazed	\$ 130.00	\$ 260.00 nn	\$ 130.00 X
28	Pedal brake	1	Grazed		\$ 80.00	\$ 80.00 -
29	Cover rear LH	1	Grazed/Cut		\$ 170.00	\$ 170.00 -
30	Flasher light rear LH/RH	2 1	LH Grazed	\$ 90.00	\$ 180.00 70-	\$ 90.00
31	Exhaust protector	1	Dented/Grazed		\$ 170.00 170-	\$ 170.00
32	Exhaust cap	1	Dented/Grazed		\$ 60.00	\$ 60.00 -
33	Exhaust muffler	1	Dented/Grazed		\$ 790.00 600-	\$ 790.00

Total:	\$ 10,629.00	\$ 8,252.00
-10%	\$ 1,062.90	\$ 825.20
List total:	\$ 9,566.10	\$ 7,426.80

1	Carbon fibre air deflector	1	Grazed/Cracked		\$ 250.00 200-	\$ 250.00
2	Number plate sticker	1	Not Necessary		\$ 20.00	-
3	Barend mirror	1set	Dented/Missing		\$ 420.00	\$ 420.00
4	Clutch lever	1	Dented/Grazed		\$ 180.00 80-	\$ 180.00



Vehicle No: FBR4926]

Report No: AAS/2021/262

5	Brake lever	1	Dented/Grazed	\$ 180.00	80 ✓	\$ 180.00
6	Tyre	1	Refit	\$ 165.00		-
7	Handle grip	1set	LH Torn	\$ 40.00		\$ 40.00 ✓
8	IU unit	1	Grazed/Cut	\$ 270.00		-
9	IU sticker	1	Torn	\$ 12.00	n/n	\$ 12.00 ✗

Special nett total: \$ 1,537.00 \$ 1,082.00

Parts Total: \$ 11,103.10 \$ 8,508.80

S/N	Labour Description	Repairer's Est	Revised Est
1	To renew & realign front fork.	\$ 200.00	\$ 150.00 ✓
2	To renew front rim & tyre.	\$ 40.00	-
3	To check all lightings & wirings.	\$ 50.00	\$ 30.00 ✓
4	To dismantle & renew damaged parts. Re-align all affected area.	\$ 800.00	400, \$ 600.00
5	Towing charge.	\$ 45.00	\$ 45.00 ✓
Labour Total:		<u>\$ 1,135.00</u>	<u>\$ 825.00</u>

Grand Total: \$ 12,238.10 \$ 9,333.80

The final adjusted lump sum amount is \$7,450.00

Under normal circumstances, the repair should be completed within a reasonable period of 4 working days

207 Photographs were taken at the time of inspection.