

Your Ref: 2021 - 79

Date: 11th April 2021

Our Ref: CS1/SCD22002761/Eqy3e2

M/s Singapore Civil Defence Force (MHA05)
91 Ubi Ave 4
Singapore 408827

Attn: Ralf Tay Gim Chye

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBR 4926J
INSURED VEHICLE: QX 1255Y
ACCIDENT DATE: 06/09/2021

We thank you for your instruction on 25/03/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBR 4926J from M/s Absolute Appraisal Services Pte Ltd.
- b) Final Repair Bill of FBR 4926J from M/s Motorplex.
- c) Singapore Accident Statement and Police Report of Vehicles FBR 4926J.
- d) Colour damaged vehicle photographs of FBR 4926J.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FBR 4926J
Make & Model : Yamaha R15 ABS (Motorcycle)
Chassis Number : ME1RG6713L0022186
Year of Registration : 2020
Engine Capacity : 155 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 4926J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER	CRACKED	160.00	110.00
1	WHEEL RIM FRONT	REFIT	1,050.00	-
2	WHEEL BEARING @\$60.00	REFIT	120.00	-
1	WHEEL AXLE	REFIT	70.00	-
2	FRONT FORK LH / RH @\$850.00	GRAZED / BENT	1,700.00	1,000.00
1	FRONT FORK UNDER COMP	DISTORTED	620.00	250.00
1	CONE BEARING	DAMAGED	105.00	80.00
1	HEADLIGHT	GRAZED / CUT	985.00	280.00
1	HEADLIGHT COWLING	GRAZED / CUT	275.00	180.00
1	HEADLIGHT LIP LH	GRAZED / CUT	65.00	65.00
1	FRONT COWLING	GRAZED / CUT	130.00	130.00
1	VISOR	REFIT	160.00	-
2	FLASHER LIGHT FRONT LH / RH @\$90.00	BROKEN / MISSING	180.00	150.00
2	PANEL CONSOLE LH / RH @\$35.00	REFIT	70.00	-
2	SIDE PANEL LH / RH @\$375.00	GRAZED / CUT	750.00	360.00
2	SIDE PANEL INNER LH / RH @\$140.00	GRAZED / CUT (1PC ONLY)	280.00	80.00
2	LOWER PANEL LH / RH @\$210.00	GRAZED / CUT	420.00	280.00
2	STICKER LH / RH @\$30.00	NECESSARY	60.00	60.00
2	HANDLEBAR LH / RH @\$170.00	BENT	340.00	340.00
1	CROWN HANDLE	REFIT	320.00	-
2	FUEL TANK COVER LH / RH @\$150.00	N/S GRAZED	300.00	150.00
2	EMBLEM LH / RH @\$25.00	N/S NECESSARY	50.00	25.00
1	GEAR SHIFT PEDAL	BENT	95.00	95.00
2	FOOTREST FRONT LH / RH @\$65.00	GRAZED	130.00	130.00
2	FOOTREST SUPPORT LH / RH @\$190.00	NOT NECESSARY	380.00	-
2	FOOTREST REAR LH / RH @\$52.00	N/S GRAZED	104.00	52.00
2	FOOTREST BRACKET LH / RH @\$130.00	NOT NECESSARY	260.00	-
1	PEDAL BRAKE	GRAZED	80.00	80.00
1	COVER REAR LH	GRAZED / CUT	170.00	170.00
2	FLASHER LIGHT REAR LH / RH @\$90.00	N/S GRAZED	180.00	70.00

Report Ref No. CS1/SCD22002761/Eqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST PROTECTOR	DENTED / GRAZED	170.00	120.00
1	EXHAUST CAP	DENTED / GRAZED	60.00	60.00
1	EXHAUST MUFFLER	DENTED / GRAZED	790.00	600.00
	LESS 10% DISCOUNT		-1,062.90	-491.70
			9,566.10	4,425.30
	<u>SPECIAL NETT ITEMS</u>			
1	CARBON FIBRE AIR DEFLECTOR (SN)	GRAZED / CRACKED	250.00	200.00
1	NUMBER PLATE STICKER (SN)	NOT NECESSARY	20.00	-
1	SET BAREND MIRROR (SN)	DENTED / MISSING	420.00	420.00
1	CLUTCH LEVER (SN)	DENTED / GRAZED	180.00	80.00
1	BRAKE LEVER (SN)	DENTED / GRAZED	180.00	80.00
1	TYRE (SN)	REFIT	165.00	-
1	SET HANDLE GRIP (SN)	N/S TORN	40.00	40.00
1	IU UNIT (SN)	NOT NECESSARY	270.00	-
1	IU STICKER (SN)	NOT NECESSARY	12.00	-
			1,537.00	820.00
	<u>LABOUR</u>			
	TO RENEW & REALIGN FRONT FORK.		200.00	150.00
	TO RENEW FRONT RIM & TYRE.	NOT NECESSARY	40.00	-
	TO CHECK ALL LIGHTINGS & WIRINGS.		50.00	30.00
	TO DISMANTLE & RENEW DAMAGED PARTS. RE-ALIGN ALL AFFECTED AREA.		800.00	400.00
	TOWING CHARGE.		45.00	45.00
			1,135.00	625.00
GRAND TOTAL			12,238.10	5,870.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,700.00

Report Ref No. CS1/SCD22002761/Eqy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.