

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG122002762/RVY3E2

Date: 24/05/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No: -
Claimant Vehicle No : SHB5308A **Insured Vehicle No :** GBB9271R
Date of Loss: 24/03/2022 Nature of Claim: TP Claim No: CDMCG22000531

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB5308A**
Make & Model: TOYOTA PRIUS HYBRID, 1.8 (A) Engine No: 2ZRS108903
Reg. Date: 30/11/2017 (Man. Year: 2017) Chassis No: JTDKB3FUX03575400
Colour: Maroon Odometer: 411172 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Sailun 6 mm Rear Left Side: Sailun 6 mm
Front Right Side: Sailun 6 mm Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,032.20	2,017.03	8,015.17	79.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,824.00	1,380.00	3,444.00	71.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,856.20	3,397.03	11,459.17	77.13
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	14,856.20	3,000.00	11,856.20	79.81

INSPECTION

Date of Assignment: 25/03/2022
Date Inspected: 25/03/2022 Inspected At: Strides Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705
Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2022)
Parts: 144	TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB5308A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, RR BUMPER ASSY (DISC 25%)	Deformed	423.90 F	*317.93 F
2	1		*REAR BUMPER REINFORCEMENT (DISC 25%)	Bent	318.80 F	*239.10 F
3	2		*PAD, RR BUMPER, RH & LH, 1 (DISC 25%)	Necessary	7.60 F	*5.70 F
4	2		*PAD, RR BUMPER, RH & LH, 2 (DISC 25%)	Necessary	7.60 F	*5.70 F
5	2		*PAD, RR BUMPER, RH & LH, 3 (DISC 25%)	Necessary	7.60 F	*5.70 F
6	3		*PAD, RR BUMPER, CTR (DISC 25%)	Necessary	6.60 F	*4.95 F
7	2		*SEAL, RR BUMPER ARM, RH & LH (DISC 25%)	Necessary	22.00 F	*16.50 F
8	1		*CLIPS PIECE, FRT & RR BUMPER (DISC 25%) (10PCS)	Necessary	15.00 F	*11.25 F
9	1		*GUARD, RR BUMPER, LOWER (DISC 25%)	Deformed	558.30 F	*418.73 F
10	1		*FILLER, RR BUMPER, RH (DISC 25%)	Cracked	119.90 F	*89.93 F
11	1		*FILLER, RR BUMPER, LH (DISC 25%)	Cracked	119.90 F	*89.93 F
12	1		*COVER, GUARD RR BUMPER LOWER (DISC 25%)	Deformed	14.80 F	*11.10 F
13	2		*REAR BUMPER GROMMET SCREW (DISC 25%)	Necessary	4.40 F	*3.30 F
14	1		*NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	Necessary	52.30 F	*39.23 F
15	1		*NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	Necessary	52.30 F	*39.23 F
16	1		*END PANEL SUB-ASSY, BODY LOWER BACK (DISC 25%)	Bent	629.80 F	*472.35 F
17	1		*SENSOR REVERSE (SN)	Scratched	180.00 F	*180.00 F
18	1		*STRIDES LOGO (SN)	Necessary	7.80 F	*7.80 F
19	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
20	1		*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F
21	2		*STOPPER, RR BUMPER, RH & LH	Not Necessary	8.60 F	*- F
22	1		*RETAINER, RR BUMPER, RH	Not Necessary	112.70 F	*- F
23	1		*RETAINER, RR BUMPER, LH	Not Necessary	111.50 F	*- F
24	1		*SEAL, RR BUMPER, RH	Not Necessary	85.20 F	*- F
25	1		*SEAL, RR BUMPER, LH	Not Necessary	85.20 F	*- F
26	1		*ANTENNA, ELECTRICAL KEY	Not Necessary	60.30 F	*- F
27	1		*LENS & BODY, REAR COMBINATION LAMP, RH	Not Necessary	438.10 F	*- F
28	1		*LENS & BODY, REAR COMBINATION LAMP, LH	Not Necessary	438.10 F	*- F
29	1		*LENS & BODY ASSY, RR BUMPER, RH	Not Necessary	486.80 F	*- F
30	1		*LENS & BODY ASSY, RR BUMPER, LH	Not Necessary	486.80 F	*- F
31	1		*COVER, REAR COMBINATION LAMP, RH	Not Necessary	54.00 F	*- F
32	1		*COVER, REAR COMBINATION LAMP, LH	Not Necessary	54.00 F	*- F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	1		*COVER, REAR FLOOR UNDER, RH	Not Necessary	169.50 F	*- F
34	1		*COVER, REAR FLOOR UNDER, LH	Not Necessary	234.30 F	*- F
35	1		*COVER, REAR FLOOR UNDER CENTER	Not Necessary	222.60 F	*- F
36	1		*PANEL SUB-ASSY, FENDER REAR RH	Not Necessary	824.80 F	*- F
37	1		*LINER, REAR FENDER, RH	Not Necessary	135.80 F	*- F
38	1		*TAIL GATE PANEL SUB-ASSY, BACK DOOR	Not Necessary	929.60 F	*- F
39	1		*TAIL GATE WEATHERSTRIP, BACK DOOR	Not Necessary	360.70 F	*- F
40	2		*TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	Not Necessary	55.80 F	*- F
41	1		*TAIL GATE LOCK ASSY, BACK DOOR	Not Necessary	452.10 F	*- F
42	1		*TAIL GATE LOCK COVER, BACK DOOR	Not Necessary	25.30 F	*- F
43	1		*TAIL GATE STRIKER ASSY, BACK DOOR	Not Necessary	24.90 F	*- F
44	1		*NUMBER PLATE	Not Necessary	35.00 F	*- F
45	1		*NUMBER PLATE FRAME	Not Necessary	25.00 F	*- F
46	1		*SPARE TYRE PANEL, PAN, REAR FLOOR	Not Necessary	564.80 F	*- F
47	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	Repair	891.20 F	*- F
48	1		*NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	Repeated	52.30 F	*- F

F=Franchise part.

Total Parts (\$\$) 10,032.20 2,017.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,852.00	700.00
2	SPRAY PAINT	New	2,232.00	600.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO REPLACE SUNDRY PARTS	New	120.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	40.00
6	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	40.00
7	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	0.00
8	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
			Gross Labour Cost (\$)	4,824.00
				1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >