

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG22002764/EVY3E2

**Date:** 12/05/2022

### REFERENCE

Insured/Claimant:	TAN JUN XIANG	Policy No:	2070107044	
Date of Loss:	24/03/2022	Nature of Claim:	OD	Claim No: 1070653792SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT7929R		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Engine No:	3A92UJB1591
Reg. Date:	17/07/2020 (Man. Year: 2019)	Chassis No:	MMBSTA13AKH003402
Colour:	Red	Odometer:	31933 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,139.95	3,918.29	1,221.66	23.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,975.00	5,255.00	1,720.00	24.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,114.95</b>	<b>9,173.29</b>	<b>2,941.66</b>	<b>24.28</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>848.05</b>	<b>642.13</b>	<b>205.92</b>	<b>24.28</b>
<b>Nett Amount (S\$)</b>	<b>12,963.00</b>	<b>9,815.42</b>	<b>3,147.58</b>	<b>24.28</b>

### INSPECTION

Date of Assignment: 25/03/2022

Date Inspected: 25/03/2022 Inspected At:

Estimated Period of Repair: 8.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C EMBLEM	Necessary	40.00 FS	*40.00 FS
2	1		*REAR NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
3	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
4	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
5	1		*UNPAINTED BODYKITS	Broken	1,643.00 FS	*1,643.00 FS
6	1		*LAMP ASSY, COMB, RR LH	Cracked	337.00 FL	*337.00 FL
7	1		*LAMP ASSY, COMB, RR RH	Not Necessary	337.00 FL	*- FL
8	1		*LAMP ASSY, LICENSE PLATE	Not Necessary	51.00 FL	*- FL
9	1		*BRACKET, RR BUMPER, LH	Broken	28.00 FL	*28.00 FL
10	1		*BRACKET, RR BUMPER, RH	Not Necessary	28.00 FL	*- FL
11	1		*FACE, RR BUMPER	Dented	751.00 FL	*751.00 FL
12	1		*PANEL, RR END	Dented	427.00 FL	*427.00 FL
13	1		*PANEL, TRUNK LID	Dented	795.00 FL	*795.00 FL
14	1		*WEATHERSTRIP, TRUNK LID	Crushed	157.00 FL	*157.00 FL
15	1		*HINGE, TRUNK LID, LH	Repair	203.00 FL	*- FL
16	1		*HINGE, TRUNK LID, RH	Repair	203.00 FL	*- FL
17	1		*GARNISH, RR END PANEL	Not Necessary	336.00 FL	*- FL
18	1		*MARK, ATTRAGE	Necessary	21.00 FL	*21.00 FL
19	1		*MARK, THREE-DIA	Necessary	70.00 FL	*70.00 FL
20	1		*TRIM, RR END	Crushed	66.00 FL	*66.00 FL
21	1		*BOARD, TRUNK ROOM FLOOR	Broken	195.00 FL	*195.00 FL
22	1		*EMBLEM MIVEC TECHNOLOGY	Not Necessary	30.00 FS	-
23	1		*GROMMET (x10) (Supplementary)	Necessary	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,068.00	4,580.00
- List Item Discount on L Items 23.00/23.00% (\$)	928.05	661.71
Total Parts (\$)	5,139.95	3,918.29

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE REAR BUMPER PANEL, BOOT, END PANEL, BODY KIT & AFFECTED AREA. REPAIR ON REAR LH FENDER & FLOOR PANEL	New	3,150.00	2,250.00
2	PAINT WORK ON REAR BUMPER, BOOT, BOTH REAR FENDER, END PANEL, FLOOR PANEL & BODY KIT	New	2,450.00	1,750.00
3	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	80.00
4	REMOVE & REPLACE BODY KIT	New	80.00	80.00
5	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	120.00
6	TO TRANSFER BOOT ATTACHMENT TO NEW PANEL	New	120.00	120.00
7	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	40.00
8	PERFORM RUST PREVENTION	New	80.00	40.00
9	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
10	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
11	REPAIR RH REAR FENDER (Supplementary)	New	275.00	275.00
12	RESPRAY ON RH REAR FENDER (Supplementary)	New	350.00	350.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,975.00</b>	<b>5,255.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >