

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22002765/EPA3Q2**Date:** 28/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210031403
<b>Claimant Vehicle No :</b>	SME2013U	<b>Insured Vehicle No :</b>	SFA808K
Date of Loss:	18/03/2022	Nature of Claim:	TP
		Claim No:	3042563543SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SME2013U</b>		
Make & Model:	BMW 230I, 2.0 COUPE (A)	Engine No:	F2823101B48B20B
Reg. Date:	21/09/2018 (Man. Year: 2018)	Chassis No:	WBA2H72090VB27730
Colour:	Blue	Odometer:	41207 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	265/35 R18	Rear Tyre Size:	265/35 R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,906.39	4,297.76	4,608.63	51.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,755.00	6,820.00	2,935.00	30.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>18,661.39</b>	<b>11,117.76</b>	<b>7,543.63</b>	<b>40.42</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment:	25/03/2022		
Date Inspected:	25/03/2022	Inspected At:	BIS Automobiles Pte Ltd (HQ) 30 Teban Gardens Crescent Singapore 608927
Estimated Period of Repair:	7.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*BUMPER TRIM -M	Dented	1,014.40 FS	*963.68 FS
3	1		*ADHESIVE SET K6 (SET)	Necessary	53.05 FS	*50.40 FS
4	1		*SET ,MOUNTS PDC SENSOR ,REAR (-M-)	Necessary	59.95 FS	*56.96 FS
5	1		*FLAP ,TOWING EYE ,PRIMED	Missing	39.35 FS	*37.39 FS
6	1		*INSERT ,BUMPER ,REAR (-M-)	Broken	253.60 FS	*240.92 FS
7	1		*GUIDE,CENTRE REAR	Broken	161.15 FS	*153.10 FS
8	1		*GUIDE FOR BUMPER ,SIDE ,LEFT	Not Necessary	153.50 FS	*- FS
9	1		*GUIDE FOR BUMPER ,SIDE ,RIGHT	Broken	153.50 FS	*145.83 FS
10	1		*EXPANDING NUT (ST 4.8) (2 PCS)	Necessary	1.10 FS	*1.05 FS
11	8		*FILLISTER HEAD SCREW (ST5X)	Necessary	8.56 FS	*7.60 FS
12	4		*HEX NUT WITH PLATE (M6)	Necessary	7.20 FS	*6.84 FS
13	1		*CARRIER ,BUMPER REAR	Dented	418.55 FS	*397.63 FS
14	2		*PLAQUE (BMW 74MM)	Necessary	72.85 FS	*1.90 FS
15	1		*GROMMET (2 PCS)	Necessary	1.60 FS	*1.52 FS
16	4		*ULTRASONIC SENSOR ESTORIL BLUE 2 (WB45)	Broken	1,484.80 FS	*352.64 FS
17	1		*DECOUPLING RING PDC TORQ (4 PCS)	Necessary	20.60 FS	*19.57 FS
18	1		*REAR LIGHT LED RIGHT	Broken	512.80 FS	*487.16 FS
19	1		*REAR LIGHT LED LEFT	Not Necessary	512.80 FS	*- FS
20	1		*REFLECTOR LEFT	Not Necessary	37.90 FS	*- FS
21	1		*REFLECTOR RIGHT	Broken	37.90 FS	*36.01 FS
22	1		*ADHESIVE TAPE (-M-)	Not Necessary	51.10 FS	*- FS
23	1		*TRUNK LID	Dented	1,147.55 FS	*1,090.18 FS
24	1		*LEFT TRUNK LID HINGE	Not Necessary	67.05 FS	*- FS
25	1		*RIGHT TRUNK LID HINGE	Not Necessary	67.05 FS	*- FS
26	2		*GAS PRESSURIZED SPRING TRUNK LID	Not Necessary	250.60 FS	*- FS
27	2		*STOP BUFFER	Not Necessary	26.40 FS	*- FS
28	1		*TRUNK LID GASKET	Not Necessary	126.80 FS	*- FS
29	1		*EXTENSION UNDERBODY PANELLING SIDE RIGHT	Not Necessary	84.75 FS	*- FS
30	1		*TAIL TRIM	Not Necessary	502.45 FS	*- FS
31	1		*M PERFORMANCE REAR SPOILER CARBON	Not Necessary	1,330.10 FS	*- FS
32	1		*ADHESIVE 1K FOR REAR SPOILER	Necessary	97.38 FS	*97.38 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **8,906.39**      **4,297.76**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER AND ATTACHMENTS TAIL END PANEL BOOT LID INCLUDE MAKING GOOD THE REAR RH FENDER AND KNOCKING OUT CAUSED BY THE ACCIDENT	New	4,320.00	2,520.00
2	TO SPRAY PAINT REAR BUMPER ,TAIL END PANEL ,BOOT LID AND REAR RH FENDER	New	3,000.00	3,000.00
3	TO REPLACE REAR BUMPER PDC SENSORS AND CONNECTORS INCLUDE PROGRAMMING AND CONDUCTING CHECKS FOR PROPER FUNCTION	New	360.00	280.00
4	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	225.00	180.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOT LID INCLUDE CONDUCTING CHECKS ON ALL DOORS CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	450.00	360.00
6	TO RECONNECT ALL ELECTRICAL COMPONENTS AND WIRINGS AT THE REAR SECTION INCLUDE CONDUCTING CHECKS FOR PROPER	New	350.00	0.00
7	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	450.00	0.00
8	TO CARRY OUT BODY CAVITY PRESERVATION	New	100.00	80.00
9	TO CARRY OUT DIAGNOSIS TESTS	New	500.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>9,755.00</b>	<b>6,820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >