

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22002774/UVY3E2

Date: 16/04/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001927213

Claimant Vehicle No : YP2879M

Insured Vehicle No : SDL6714Z

Date of Loss: 11/03/2022

Nature of Claim: TP

Claim No: 271093

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP2879M**

Make & Model: MITSUBISHI FUSO, 7.5 D FM65FM2RDEB (M)

Engine No: 6M60215448

Reg. Date: 17/06/2016 (Man. Year: 2016)

Chassis No: FM65FMA30103

Colour: White

Odometer: 182143 km

Engine Capacity: 7545 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Austone 7 mm

Rear Left Side: Austone 7/7 mm

Front Right Side: Austone 7 mm

Rear Right Side: Austone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,658.80	2,451.73	2,207.07	47.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,070.00	630.00	37.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,358.80	3,521.73	2,837.07	44.62
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	6,358.80	2,800.00	3,558.80	55.97
+ GST 7.00/7.00% (S\$)	445.12	196.00	249.12	55.97
Nett Amount (S\$)	6,803.92	2,996.00	3,807.92	55.97

INSPECTION

Date of Assignment: 25/03/2022

Date Inspected: 25/03/2022 Inspected At:

Liu's Brother Auto Workshop (HQ)
1 Kaki Bukit Ave 6 #01-01, Auto Bay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Mar 2022)	
Parts:	N/A	mitsubishi fuso 7.5 D FM65FM2RDEB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP2879M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH HEAD LAMP	Cracked	1,302.40 F	*1,005.25 FL
2	1		*FRONT BUMPER SIDE	Cracked	497.40 F	*435.10 FL
3	1		*FRONT LH CORNER PANEL	Cracked	1,183.70 F	*1,183.63 FL
4	1		*FRONT LH CORNER PANEL SIGNAL LAMP	Not Necessary	293.30 F	*- FL
5	1		*FRONT LH STEP PANEL GARNISH	Cracked	657.00 F	*645.00 FL
6	1		*FRONT LH SIDE PANEL	Repair	725.00 F	*- FL
					Sub Total (\$\$)	4,658.80 3,268.98
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 817.25
					Total Parts (\$\$)	4,658.80 2,451.73

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	550.00
3	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	50.00	0.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	800.00	500.00
Gross Labour Cost (\$\$)			1,700.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >