

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22002776/GNY3E2

Date: 11/08/2022

REFERENCE

Insured/Claimant: MARCUS TEO LIWEI Policy No: MPC21P00196800
Date of Loss: 24/03/2022 Nature of Claim: OD Claim No: DMPC2200118H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB8713Y**
Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B6023721
Reg. Date: 17/09/2021 (Man. Year: 2019) Chassis No: GK82103191
Colour: Blue Odometer: 9632 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$105,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,785.50	10,898.50	887.00	7.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	1,120.00	340.00	23.29
Paintwork Labour	980.00	900.00	80.00	8.16
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,225.50	12,918.50	1,307.00	9.19
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	14,225.50	12,168.50	2,057.00	14.46
+ GST 7.00/7.00% (S\$)	995.79	851.80	143.99	14.46
Nett Amount (S\$)	15,221.29	13,020.30	2,200.99	14.46

INSPECTION

Date of Assignment: 25/03/2022 Present Location: Vin's Motor Pte Ltd (Sin Ming)
Date Inspected: 25/03/2022 Inspected At: Vin's Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive, #03-03, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Aug 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB8713Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bonnet (WCP)	Buckled	540.00 F	*540.00 F
2	1		*Front bonnet RH hinge (WCP)	Bent	30.00 F	*30.00 F
3	1		*Front bonnet LH hinge (WCP)	Bent	30.00 F	*30.00 F
4	1		*Front bonnet rubber (WCP)	Twisted	25.00 F	*25.00 F
5	1		*Front bonnet insulator (WCP)	Torn	80.00 F	*80.00 F
6	1		*Front bonnet lower lock (WCP)	Bent	90.00 F	*90.00 F
7	1		*Front bonnet lock cover (WCP)	Deformed	50.00 F	*50.00 F
8	1		*Front RH headlamp (WCP)	Broken	1,100.00 F	*1,100.00 F
9	1		*Front LH headlamp (WCP)	Broken	1,100.00 F	*1,100.00 F
10	1		*Front RH headlamp lower bracket (WCP)	Broken	30.00 F	*30.00 F
11	1		*Front LH headlamp lower bracket (WCP)	Broken	30.00 F	*30.00 F
12	1		*Front grille base (WCP)	Broken	200.00 F	*200.00 F
13	1		*Front grille outer chrome garnish (WCP)	Broken	240.00 F	*240.00 F
14	1		*Front grille emblem (WCP)	Cracked	230.00 F	*230.00 F
15	1		*Front grille emblem housing (WCP)	Cut	20.00 F	*20.00 F
16	1		*Front grille lower chrome moulding (WCP)	Broken	140.00 F	*140.00 F
17	1		*Front bumper (WCP)	Deformed	730.00 F	*730.00 F
18	1		*Front bumper towing cover (WCP)	Not Necessary	20.00 F	*- F
19	1		*Front bumper centre lower grille (WCP)	Broken	80.00 F	*80.00 F
20	1		*Front bumper RH side grille (WCP)	Deformed	60.00 F	*60.00 F
21	1		*Front bumper LH side grille (WCP)	Broken	60.00 F	*60.00 F
22	1		*Front bumper under cover (WCP)	Broken	190.00 F	*190.00 F
23	1		*Front bumper RH side retainer (WCP)	Deformed	10.00 F	*10.00 F
24	1		*Front bumper LH side retainer (WCP)	Deformed	10.00 F	*10.00 F
25	1		*Front bumper reinforcement (WCP)	Bent	250.00 F	*250.00 F
26	10		*Front bumper clips @ \$3.00 (WCP)	Necessary	30.00 F	*30.00 F
27	1		*Front support panel (WCP)	Bent	420.00 F	*420.00 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*Front support panel top cover (WCP)	Cut	40.00 F	*40.00 F
29	1		*Front support panel air duct (WCP)	Cracked	40.00 F	*40.00 F
30	1		*Aircon condenser (WCP)	Cut	600.00 F	*600.00 F
31	1		*Radiator (WCP)	Not Necessary	750.00 F	*- F
32	1		*Front radar (WCP)	Broken	1,050.00 F	*1,050.00 F
33	1		*Front radar bracket (WCP)	Bent	530.00 F	*530.00 F
34	1		*Battery cover (Red) (WCP)	Cut	10.00 F	*10.00 F
35	1		*Front RH fender (WCP)	Buckled	180.00 F	*180.00 F
36	1		*Front LH fender (WCP)	Buckled	180.00 F	*180.00 F
37	1		*Front windscreen glass (WCP)	Cracked	1,200.00 F	*1,200.00 F
38	1		*Front windscreen glass moulding (WCP)	Necessary	70.00 F	*70.00 F
39	1		*Front wiper grille garnish (WCP)	Cut	160.00 F	*160.00 F
40	1		*Front no. plate	Bent	40.00 FS	*40.00 FS
41	1		*Front windscreen gum	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	10,725.00	9,915.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,060.50	983.50
Total Parts (\$\$)	11,785.50	10,898.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray painting	New	980.00	900.00
<u>Labour Items</u>				
2	To remove and refix windscreen	New	150.00	120.00
3	To reset headlamp system	New	250.00	80.00
4	To reset radar system	New	280.00	220.00
5	To repair damages	New	780.00	700.00
			Gross Labour Cost (\$)	2,440.00
				2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >