

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22002777/VTCE2

**Date:** 24/06/2022

### REFERENCE

Insured/Claimant:	NG AIK GIAN (HUANG YIYAN)	Policy No:	1800019009	
Date of Loss:	19/03/2022	Nature of Claim:	OD	Claim No: 8676863833SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW7944S		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK049776
Reg. Date:	01/03/2018 (Man. Year: 2017)	Chassis No:	WAUZZZF4XJA069086
Colour:	Grey	Odometer:	83363 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$114,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,179.00	7,766.64	32,412.36	80.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,972.00	2,772.00	6,200.00	69.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>49,151.00</b>	<b>10,538.64</b>	<b>38,612.36</b>	<b>78.56</b>
<b>- Excess (S\$)</b>	<b>550.00</b>	<b>550.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>48,601.00</b>	<b>9,988.64</b>	<b>38,612.36</b>	<b>79.45</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>3,402.07</b>	<b>699.20</b>	<b>2,702.87</b>	<b>79.45</b>
<b>Nett Amount (S\$)</b>	<b>52,003.07</b>	<b>10,687.84</b>	<b>41,315.23</b>	<b>79.45</b>

### INSPECTION

Date of Assignment:	25/03/2022		
Date Inspected:	25/03/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT CENTRE GRILLE CENTRE	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	Not Necessary	254.00 FS	*- FS
6	2		*FRONT BUMPER INNER AIR GUIDE LH / RH	Not Necessary	144.00 FS	*- FS
7	1		*RADIATOR GRILLE	Dented	2,421.00 FS	*1,936.80 FS
8	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	899.00 FS	*719.20 FS
9	1		*FRONT BUMPER FOAM FILLER	Cut	139.00 FS	*110.80 FS
10	2		*FRONT BUMPER BRACKET LH / RH	Serviceable	508.00 FS	*- FS
11	2		*FRONT BUMPER GUIDE SECTION LH / RH	Serviceable	82.00 FS	*- FS
12	1		*FRONT BUMPER TOP COVER	Necessary	143.00 FS	*114.00 FS
13	1		*STICKER SIGNAGE CAUTION	Necessary	16.00 FS	*12.40 FS
14	1		*STICKER AIR CONDITIONER	Necessary	9.00 FS	*6.64 FS
15	1		*LOCK CARRIER BRACKET	Serviceable	154.00 FS	*- FS
16	2		*LOCK CARRIER SUPPORT LH	Cut	64.00 FS	*51.04 FS
17	2		*REVERSE SENSOR FRONT INNER / OUTER	Serviceable	530.00 FS	*- FS
18	4		*SEAL RING	Serviceable	10.00 FS	*- FS
19	1		*WIRING SET FOR BUMPER	Serviceable	567.00 FS	*- FS
20	1		*FANFARE HIGH TONE LH	Serviceable	134.00 FS	*- FS
21	1		*FANFARE LOW TONE RH	Serviceable	139.00 FS	*- FS
22	2		*SPRING SHACKLE LH / RH	Serviceable	66.00 FS	*- FS
23	1		*BONNET	Dented	3,425.00 FS	*2,740.00 FS
24	1		*BONNET ATTACHMENT PARTS	Serviceable	431.00 FS	*- FS
25	3		*BONNET IMPACT PROTECTION CENTRE LH / RH	Necessary	93.00 FS	*73.20 FS
26	2		*BONNET COVER LH / RH	Serviceable	52.00 FS	*- FS
27	2		*BONNET STRIKER LH / RH	Serviceable	112.00 FS	*- FS
28	2		*BONNET LID LOCK	Serviceable	455.00 FS	*- FS
29	1		*BOWDEN CABLE	Serviceable	64.00 FS	*- FS
30	1		*RELEASE LEVER	Serviceable	15.00 FS	*- FS
31	1		*BOWDEN CABLE CENTRE	Serviceable	64.00 FS	*- FS
32	1		*COVER	Serviceable	11.00 FS	*- FS
33	2		*WHEEL HOUSING LINER LH / RH	Serviceable	522.00 FS	*- FS
34	2		*WHEEL SPOILER LH / RH	Serviceable	164.00 FS	*- FS
35	2		*LED HEADLIGHT LH / RH	Serviceable	16,588.00 FS	*- FS
36	2		*LIFT CYLINDER LH / RH	Serviceable	462.00 FS	*- FS
37	1		*CORRUGATED PIPE	Serviceable	107.00 FS	*- FS
38	2		*LIFT CYLINDER BRACKET	Serviceable	14.00 FS	*- FS
39	1		*LOCK CARRIER	Serviceable	1,127.00 FS	*- FS
40	2		*RADIATOR SUPPORT	Serviceable	85.00 FS	*- FS
41	1		*CHARGE AIR COOLER	Serviceable	654.00 FS	*- FS
42	1		*AIRCON CONDENSER	Serviceable	683.00 FS	*- FS
43	1		*O RING	Serviceable	11.00 FS	*- FS
44	1		*SEAL RING SIZE 11X2	Serviceable	12.00 FS	*- FS
45	1		*SEAL RING SIZE 9.5X5	Serviceable	11.00 FS	*- FS
46	1		*RADIATOR BRACKET	Cut	21.00 FS	*16.32 FS
47	1		*RADIATOR	Serviceable	1,010.00 FS	*- FS
48	6		*COOLANT 1.0 L	Serviceable	282.00 FS	*- FS
49	2		*RADIATOR AIR GUIDE INNER LH / RH	Serviceable	64.00 FS	*- FS
50	2		*RADIATOR AIR GUIDE OUTER LH / RH	Serviceable	28.00 FS	*- FS
51	2		*RADIATOR AIR GUIDE LOWER LH / RH	Serviceable	44.00 FS	*- FS
52	1		*FAN RING	Serviceable	291.00 FS	*- FS
53	1		*RADIATOR FAN WITH CONTROL UNIT	Serviceable	2,483.00 FS	*- FS
54	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
55	1		*SUNDRIES	Necessary	350.00 FS	*24.64 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	2		*FRONT BUMPER OUTER AIR GUIDE GRILLE	Not Necessary	818.00 FS	*- FS
F=Franchise part. S=SpcNett.						
				<b>Total Parts (\$\$)</b>	<b>40,179.00</b>	<b>7,766.64</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	0.00
3	TO REMOVE AND RENEW AIR CON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE VACUUM AND REGAS	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	1,100.00
5	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,000.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,972.00</b>	<b>2,772.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >