

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002779/KVY3N2**Date:** 29/04/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00049562100

**Claimant Vehicle
No :** EX89J**Insured Vehicle
No :** GBF8458E

Date of Loss: 22/03/2022

Nature of Claim: TP

Claim
No: SNM22D202011/C02/LEWLC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **EX89J**

Make & Model: BMW 525i, 2.5 (A)

Reg. Date: 27/11/2008 (Man. Year: 2008)

Colour: Metallic Black

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 79374373N52B25AF

Chassis No: WBANU52010CZ89717

Odometer: 311455 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35ZR19

Front Left Side: Pirelli 8 mm

Front Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

Rear Tyre Size:

Rear Left Side:

Rear Right Side:

275/30ZR19

Pirelli 7 mm

Pirelli 7 mm

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,592.15	5,240.45	9,351.70	64.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,230.00	1,170.00	48.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,992.15	6,470.45	10,521.70	61.92
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	16,992.15	4,900.00	12,092.15	71.16
+ GST 7.00/7.00% (S\$)	1,189.45	343.00	846.45	71.16
Nett Amount (S\$)	18,181.60	5,243.00	12,938.60	71.16

INSPECTION

Date of Assignment: 25/03/2022

Date Inspected: 25/03/2022 Inspected At:

Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Apr 2022)
Parts:	143	BMW 525I 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EX89J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*TAILLAMP	Serviceable	1,908.00 FL	*- FL
2	2		*TAILLAMP WEATHERSEAL	Serviceable	92.00 FL	*- FL
3	2		*TAILLAMP PANEL	Repair	482.00 FL	*- FL
4	1		*REAR BUMPER	Buckled	1,295.00 FL	*1,295.00 FL
5	1		*REAR BUMPER TOW HOOK COVER	Missing	59.00 FL	*59.00 FL
6	2		*REAR BUMPER SIDE CARRIER	Serviceable	570.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	915.00 FL	*640.90 FL
8	2		*REAR BUMPER REINFORCEMENT BRACKET	Cracked	422.00 FL	*422.00 FL
9	1		*REAR BUMPER UPPER CARRIER BRACKET	Cracked	382.00 FL	*195.10 FL
10	1		*REAR BUMPER LOWER CARRIER BRACKET	Serviceable	449.00 FL	*- FL
11	1		*BOOTLID	Repair	1,398.00 FL	*- FL
12	1		*BOOTLID LOCK	Repair	417.00 FL	*- FL
13	1		*EXHAUST PIPE	O/s Bent	2,090.00 FL	*1,045.00 FL
14	1		*EXHAUST PIPE CHROME TIP (4 Pcs)	O/s Dented	1,140.00 FL	*210.00 FL
15	2		*EXHAUST PIPE HOLDER	Serviceable	96.00 FL	*- FL
16	2		*EXHAUST PIPE HEATSHIELD	Repair	276.00 FL	*- FL
17	1		*END PANEL TOP GARNISH	Serviceable	323.00 FL	*- FL
18	1		*END PANEL	Repair	899.00 FL	*- FL
19	1		*BOOTLID LOGO	Necessary	109.00 FL	*109.00 FL
20	1		*BOOTLID 525I EMBLEM	Necessary	75.00 FL	*75.00 FL
21	2		*REVERSE SENSOR HOLDER	Necessary	36.00 FS	*36.00 FS
22	2		*REVERSE SENSOR (FACTORY ORIGINAL)	Shorted	760.00 FS	*490.00 FS
23	1		*REAR BUMPER DIFFUSER	Cracked	800.00 FS	*800.00 FS
24	12		*REAR BUMPER CLIPS	Necessary	66.00 FS	*66.00 FS
25	6		*END PANEL TOP GARNISH CLIPS	Not Necessary	33.00 FS	*- FS
26	1		*END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
27	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,262.00	5,443.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	669.85	202.55
Total Parts (\$\$)	14,592.15	5,240.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	550.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	100.00	20.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,000.00	660.00
4	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (\$\$)			2,400.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >