

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22002784/UQY3N2**Date:** 13/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00017972102

**Claimant Vehicle No :** SMK8725C **Insured Vehicle No :** PC3934E

Date of Loss: 15/03/2022 Nature of Claim: TP Claim No: SNM22D201817/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMK8725C**

Make & Model: MAZDA CX-5, 2.0 PREMIUM 2WD I2 (A) Engine No: PE31344417

Reg. Date: 26/04/2019 (Man. Year: 2019) Chassis No: JM6KF2W7AK0314874

Colour: Grey Odometer: 37917 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/65R17 Rear Tyre Size: 225/65R17

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,635.30	4,596.90	1,038.40	18.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,310.00	2,700.00	1,610.00	37.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,945.30</b>	<b>7,296.90</b>	<b>2,648.40</b>	<b>26.63</b>
<b>+ GST 7.00/7.00% (S\$)</b>	696.17	510.78	185.39	26.63
<b>Nett Amount (S\$)</b>	<b>10,641.47</b>	<b>7,807.68</b>	<b>2,833.79</b>	<b>26.63</b>

**INSPECTION**

Date of Assignment: 25/03/2022

Date Inspected: 31/03/2022 Inspected At: Trans Eurokars Pte Ltd (Ubi)  
5 Ubi Close  
Singapore 408605

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 May 2022)
<b>Parts:</b>	M1-SUV	MAZDA CX-5 2.0 PREMIUM 2WD I2 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMK8725C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	1,023.10 FS	*1,023.10 FS
2	1		*STIFF.A, FRT BUMPER	Not Necessary	115.50 FS	*- FS
3	1		*FOAM, BUMPER KF	Not Necessary	47.80 FS	*- FS
4	2		*FASTENER FOAM	Not Necessary	12.40 FS	*- FS
5	1		*REINFORCEMENT FRT	Repair	614.10 FS	*- FS
6	1		*PLATE, SET FRONT	Torn	160.20 FS	*160.20 FS
7	2		*FASTENER	Necessary	6.40 FS	*6.40 FS
8	1		*FRONT GRILLE, RADIATOR	Cracked	1,566.40 FS	*1,566.40 FS
9	1		*BRACKET MASCOT FRT	Cracked	92.10 FS	*92.10 FS
10	1		*MASCOT FRT	Not Necessary	95.10 FS	*- FS
11	1		*BRACKET TOP FRT GRILLE	Damaged	109.00 FS	*109.00 FS
12	1		*FRONT GRILLE RAD TOP	Dented	299.30 FS	*299.30 FS
13	1		*COVER GRILLE TOP RH	Not Necessary	15.80 FS	*- FS
14	1		*COVER GRILLE TOP LH	Not Necessary	15.80 FS	*- FS
15	14		*FASTENER FOAM	Necessary	56.00 FS	*56.00 FS
16	8		*RIVET	Necessary	73.60 FS	*73.60 FS
17	1		*LABEL,CAUTION	Not Necessary	3.50 FS	*- FS
18	1		*LABEL,CAUTION	Not Necessary	3.50 FS	*- FS
19	1		*BONNET	Dented	1,076.30 FS	*1,076.30 FS
20	1		*WEATHERSTRIP BONNET OUTER	Serviceable	42.90 FS	*- FS
21	5		*FASTENER	Necessary	12.00 FS	*12.00 FS
22	1		*WEATHERSTRIP BONNET INNER	Not Necessary	42.00 FS	*- FS
23	5		*FASTENER	Necessary	17.00 FS	*17.00 FS
24	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
25	1		*CAP R	Cut	15.50 FS	*15.50 FS
26	1		*FRONT NUMBER PLATE	Bent	70.00 FS	*70.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>5,635.30</b>	<b>4,596.90</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER AND BONNET	New	1,500.00	990.00
2	TO RESPRAY FRONT BUMPER, FRONT GRILLE RAD TOP AND BONNET	New	1,600.00	1,260.00
3	TO TRANSFER FRONT PEDESTRIAN SENSORS	New	660.00	180.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	300.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,310.00</b>	<b>2,700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >