

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22002785/KQY3Q2**Date:** 14/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00040642201

**Claimant Vehicle No :** SLX4966T **Insured Vehicle No :** SBL8822E

Date of Loss: 24/03/2022 Nature of Claim: TP Claim No: SNM22D202056/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLX4966T**

Make & Model: KIA CARENS, 1.7 D DCT 5DR FWD (A) Engine No: D4FDJH551006

Reg. Date: 29/03/2018 (Man. Year: 2018) Chassis No: KNAHU815VJ7203852

Colour: Metallic Grey Odometer: 324351 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Grenlander 8 mm Rear Left Side: DURATURN 8 mm

Front Right Side: Grenlander 8 mm Rear Right Side: DURATURN 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,260.60	2,335.60	925.00	28.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	900.00	1,590.00	63.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,750.60</b>	<b>3,235.60</b>	<b>2,515.00</b>	<b>43.73</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,550.00</b>		
<b>(S\$)</b>	5,750.60	2,550.00	3,200.60	55.66
<b>+ GST 7.00/7.00% (S\$)</b>	402.54	178.50	224.04	55.66
<b>Nett Amount (S\$)</b>	<b>6,153.14</b>	<b>2,728.50</b>	<b>3,424.64</b>	<b>55.66</b>

**INSPECTION**

Date of Assignment: 25/03/2022

Date Inspected: 29/03/2022 Inspected At: Munich Autocare Pte Ltd (HQ)  
60 Jalan Lam Huat, #07-43  
Singapore 737869

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2022)
Parts:	M1-MPV	KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX4966T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Dented	618.00 F	*618.00 FL
2	1		*FRONT HEADLAMP RH	Mtg Cracked / Cut	1,450.00 F	*1,450.00 FL
3	1		*FRONT HEADLAMP LOWER BRACKET RH	Serviceable	21.60 F	*- FL
4	1		*FRONT FENDER RH	Bent	384.00 F	*384.00 FL
5	1		*FRONT FENDER INNER COWLING	Distorted	68.00 F	*68.00 FL
6	1		*FRONT RIM RH	Serviceable	650.00 F	*- FL
7	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	14.00 F	*14.00 FL
8	6		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
9	5		*FRONT FENDER INNER COWLING CLIPS	Necessary	25.00 FS	*25.00 FS
					Sub Total (S\$)	3,260.60 2,589.00
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 253.40
					Total Parts (S\$)	3,260.60 2,335.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIX ,REPAIR ,KNOCKING WELDING ,FRONT PORTION ,FRONT BUMPER ,FRONT FENDER RH AND DAMAGE AREA	New	800.00	400.00
2	TO CHECK AND ADJUST HEADLAMP LH /RH FOCUS}	New	120.00	30.00
3	TO CHECK ALL WIRING FOR OPERATION }	New	150.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	30.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
6	TO REMOVE AND REFIX FRONT TYRE TO NEW RIM	New	100.00	0.00
7	TO RESPRAY FRONT PORTION ,FRONT BUMPER ,FRONT FENDER RH AND POLISH DAMAGE AREAS	New	1,000.00	440.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,490.00</b>	<b>900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >