

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22002786/UQY3E2
Date: 31/05/2022

REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : GBD6267M **Insured Vehicle No :** SNB8713Y
Date of Loss: 24/03/2022 Nature of Claim: TP Claim No: DMPC2200118H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD6267M**
Make & Model: TOYOTA HIACE, 3.0 D (M) Engine No: 1KD2464682
Reg. Date: 11/02/2015 (Man. Year: 2014) Chassis No: JTFHT02P600154692
Colour: White Odometer: 211524 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,422.20	4,661.57	8,760.63	65.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	2,180.00	1,920.00	46.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,522.20	6,841.57	10,680.63	60.95
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	17,522.20	5,400.00	12,122.20	69.18

INSPECTION

Date of Assignment: 25/03/2022
Date Inspected: 26/03/2022 Inspected At: KS AUTOMOBILE (HQ)
60 JALAN LAM HUAT, CARROS CENTRE, #05-68
Singapore 737869
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 May 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD6267M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,754.00 FL	*1,754.00 FL
2	1		*TAILGATE OUTER HANDLE	Not Necessary	194.20 FL	*- FL
3	1		*TAILGATE OUTER MOULDING	Not Necessary	312.00 FL	*- FL
4	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	119.20 FL	*- FL
5	1		*TAILGATE INNER TRIM	Torn	267.60 FL	*267.60 FL
6	1		*TAILGATE WEATHERSTRIP	Twisted	368.00 FL	*368.00 FL
7	1		*TAILGATE WEATHERSTRIP PROTECTOR	No such part	99.60 FL	*- FL
8	1		*TAILGATE INNER LOCK	Dented / Jammed	257.60 FL	*257.60 FL
9	1		*TAILGATE LOWER LOCK	Not fitted	100.20 FL	*- FL
10	1		*TAILGATE KEY LOCK	Not Necessary	241.60 FL	*- FL
11	1		*TAILGATE WINDSCREEN RUBBER	No such part	294.00 FL	*- FL
12	1		*TAILGATE LOGO	Necessary	59.00 FL	*59.00 FL
13	1		*TAILGATE INNER TOP TRAM	Not Necessary	284.00 FL	*- FL
14	1		*TAIL GATE CAMERA	Not Necessary	845.00 FL	*- FL
15	2		*TAIL LAMP	Cracked	595.20 FL	*595.20 FL
16	1		*TAIL LAMP PANEL RH	Dented	387.90 FL	*387.90 FL
17	1		*REAR FLOOR MAT	Not Necessary	800.00 FL	*- FL
18	1		*REAR BUMPER	Distorted	598.00 FL	*461.10 FL
19	2		*REAR BUMPER SIDE RETAINER	Bent / Cracked	134.40 FL	*134.40 FL
20	1		*REAR FENDER INNER PANEL	Repair	679.40 FL	*- FL
21	1		*REAR END PANEL (INNER)	Badly Dented	547.10 FL	*547.10 FL
22	1		*REAR END PANEL (OUTER)	Badly Dented	850.20 FL	*850.20 FL
23	2		*REAR END PANEL EXTEND PANEL	No such part	797.40 FL	*- FL
24	1		*REAR FLOOR PANEL	Repair	2,298.00 FL	*- FL
25	1		*REAR EXHAUST PIPE	Repair	898.00 FL	*- FL
26	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	56.00 FL	*- FL
27	1		*REAR NUMBER PLATE	Bent	50.00 FS	*20.00 FS
28	1		*SET REAR BUMPER CLIP	Necessary	52.00 FS	*40.00 FS
29	1		*SET REAR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
30	1		*SET TAILGATE INNER BOARD CLIP	Necessary	52.00 FS	*40.00 FS
31	1		*TAILGATE SEALANT	Not Necessary	80.00 FS	*- FS
32	1		*TAILGATE STICKER 70KM/H	Necessary	20.00 FS	*10.00 FS
33	1		*SET TAILGATE COMPANY STICKER	Not fitted	200.00 FS	*- FS
34	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
35	1		*REAR END PANEL TOP PLATE	Repair	300.00 FS	*- FS
36	1		*REAR END PANEL EXTEND PANEL SEALANT	Not Necessary	80.00 FS	*- FS
37	1		*REAR FLOOR PANEL TOP WOODEN (SPECIAL TYPE)	Not Necessary	600.00 FS	*- FS
38	1		*REAR FENDER INNER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
39	1		*REAR FLOOR PANEL SEALANT	Not Necessary	100.00 FS	*- FS
40	1		*REAR FLOOR TOP BOARD	Not Necessary	800.00 FS	*- FS
41	1		*REAR WINDSCREEN SEALANT	Necessary	300.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,881.60	6,082.10
- List Item Discount on L Items 25.00/25.00% (S\$)	3,459.40	1,420.53
Total Parts (S\$)	13,422.20	4,661.57

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND REPLACE PARTS	New	1,600.00	1,100.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	80.00
4	WIRING, BULB CHECKING	New	80.00	20.00
5	REMOVE AND REFIX TAILGATE WINDSCREEN	New	150.00	120.00
6	TRANSFER TAILGATE MECHANISM	New	120.00	60.00
7	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
8	REMOVE AND REFIX REAR EXHAUST	New	150.00	0.00
9	REAR CHASSIS ALIGNMENT	New	250.00	0.00
			Gross Labour Cost (S\$)	4,100.00
				2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >