

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22002787/ATY3N2**Date:** 24/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00003712200
<b>Claimant Vehicle No :</b>	SNB523G	<b>Insured Vehicle No :</b>	SMY4038E
Date of Loss:	23/03/2022	Nature of Claim:	TP
		Claim No:	SNM22D202012/C02/CSC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNB523G</b>	Engine No:	PY20733623
Make & Model:	MAZDA 6, 2.0 (A)	Chassis No:	JM6GJ1032G0233605
Reg. Date:	29/04/2016 (Man. Year: 2016)	Odometer:	88460 km
Colour:	Black		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/50R18	Rear Tyre Size:	225/50R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,203.40	5,705.04	3,498.36	38.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,390.00	760.00	35.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11,353.40</b>	<b>7,095.04</b>	<b>4,258.36</b>	<b>37.51</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,600.00</b>		
<b>Nett Amount (\$\$)</b>	<b>11,353.40</b>	<b>5,600.00</b>	<b>5,753.40</b>	<b>50.68</b>

**INSPECTION**

Date of Assignment:	29/03/2022	
Date Inspected:	25/03/2022 Inspected At:	Automobile Hub Enterprise 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	5.0 days	

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2022)
<b>Parts:</b>	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNB523G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,151.30 F	*1,151.30 FL
2	1		*FRONT BUMPER SIDE HOLDER LH	Damaged	45.40 F	*45.40 FL
3	1		*FRONT BUMPER FOG LAMP LH	Cracked	325.50 F	*325.50 FL
4	1		*HEADLAMP LH	Cracked	3,209.30 F	*3,209.30 FL
5	1		*HEADLAMP LOWER BRACKET LH	Not Necessary	38.50 F	*- FL
6	1		*FRONT LH FENDER	Dented	398.40 F	*398.40 FL
7	1		*FRONT LH FENDER INNER SHIELD	Deformed	195.60 F	*195.60 FL
8	1		*FRONT LH KNUCKLE ARM	Not Necessary	477.30 F	*- FL
9	1		*FRONT LH WHEEL HUB C/W BEARING	Damaged	245.40 F	*245.40 FL
10	1		*FRONT LH LOWER ARM	Bent	385.40 F	*385.40 FL
11	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
12	1		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
13	1		*FRONT LH FENDER SOUND INSULATOR	Necessary	280.00 FS	*200.00 FS
14	1		*FRONT LH SHOCK ABSORBER	Not Necessary	850.00 FS	*- FS
15	1		*FRONT LH WHEEL RIM	Cut	1,291.30 FS	*680.00 FS
16	1		*FRONT LH TYRE	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,203.40</b>	<b>6,896.30</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	1,191.26
<b>Total Parts (\$\$)</b>	<b>9,203.40</b>	<b>5,705.04</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	500.00
2	SPRAY PAINTING	New	800.00	600.00
3	WIRING	New	50.00	30.00
4	TO DISMANTLE FRONT UNDERCARRIAGE	New	350.00	180.00
5	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
<b>Gross Labour Cost (\$)</b>			<b>2,150.00</b>	<b>1,390.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >