

SNBS23G 2016 April.

TP China.

Mazda 6 2488cc

Denise.

JM6GJ1032G0233605

Front Bumper	Deformed	1151.30	✓
Front Bumper Clips	per	30(SN)	✓
Front Bumper Side Holder LH.	Deformed	45.40	✓
Front Bumper Fog Lamp LH.	Crushed	325.50	✓
Headlamp LH	Crushed	3209.30	✓
Headlamp Lower Bracket LH.	HP m	38.50	X
Front LH Fender	Dented	398.40	✓
Front LH Fender Lower Shield	Deformed	195.60	✓
Front LH Fender Lower Shield Clips	per	30(SN)	✓
Front LH Fender Sound Insulator	per	280(SN)	200(SN) ✓

SNB 5236.

Front LH Shock Absorber } 850(SN) X
NH

Front LH Knuckle Arm. } 477.30 X
NH

Front LH Wheel Hub c/w Bearing. 245.40 ✓

Front LH Lower Arm. 385.40 ✓

5859.9

4687.92

S.N: 940

Front LH Wheel Rim 1291.30. 680(SN)

Front LH Tyre. 250(SN) X

Panel Beating

Spray Painting.

Wiring.

To dismantle front undercarriage

To perform wheel alignment.

~~800~~ 500

~~800~~ 600

~~50~~ 30

~~350~~ 180.

~~150~~ 80.

Total: 701792

L/S: S.B.K.

05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: