

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB22002790/UQY3Q2**Date:** 22/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : GBK6C **Insured Vehicle No :** SLR1925M

Date of Loss: 24/03/2022 Nature of Claim: TP Claim No: MFL2022D0001444

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK6C**

Make & Model: BMW 1 SERIES, 3.0 (A) Engine No: 1KD2571923

Reg. Date: 05/05/2016 (Man. Year: 2015) Chassis No: KDH2010184085

Colour: Grey Odometer: 186190 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50Z R17 Rear Tyre Size: 215/50Z R17

Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,086.77	5,545.75	11,541.02	67.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,150.00	1,960.00	3,190.00	61.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,236.77	7,505.75	14,731.02	66.25
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	22,236.77	6,000.00	16,236.77	73.02

INSPECTION

Date of Assignment: 25/03/2022

Date Inspected: 25/03/2022 Inspected At:

Euro Success Services Pte Ltd (HQ)
1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Apr 2022)
Parts:	144	BMW 1 SERIES 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK6C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,680.40 FL	*- FL
2	1		*TAIL LAMP L/H (LED)	Broken	695.50 FL	*695.50 FL
3	1		*TAIL LAMP FILLERS PANEL INNER L/H	Repair	515.40 FL	*- FL
4	1		*TAIL LAMP FILLER PANEL OUTER L/H	Repair	598.50 FL	*- FL
5	1		*REAR BUMPER REFLECTOR L/H	Not Necessary	150.00 FL	*- FL
6	1		*REAR END OUTER PANEL L/H	Not Necessary	480.00 FL	*- FL
7	1		*REAR END PANEL INNER	Not Necessary	580.40 FL	*- FL
8	1		*REAR END PANEL TOP MOUNTING L/H	Not Necessary	250.60 FL	*- FL
9	1		*LH SIDE SKIRTING	Cut / Cracked	980.40 FL	*980.40 FL
10	1		*REAR FLOOR COMPARTMENT PANEL	Not Necessary	2,100.00 FL	*- FL
11	1		*REAR FLOOR PANEL LOWER MEMBER	Not Necessary	580.10 FL	*- FL
12	1		*REAR FENDER L/H	Badly Dented	2,450.90 FL	*2,120.10 FL
13	1		*REAR FENDER OUTER COVER L/H	Necessary	980.50 FL	*450.00 FL
14	1		*REAR FENDER INNER TRIM BOARDS L/H	Not Necessary	325.50 FL	*- FL
15	1		*REAR FENDER INNER TRIM BOARDS CLIPS	Not Necessary	135.00 FL	*- FL
16	1		*REAR BUMPER SIDE HOLDER L/H	Cracked	280.00 FL	*95.00 FL
17	1		*REAR FENDER INNER PANEL L/H	Repair	850.40 FL	*- FL
18	1		*REAR FENDER OUTER PANEL L/H	No such part	580.70 FL	*- FL
19	1		*REAR FENDER WHEEL HOUSING	Not Necessary	1,220.80 FL	*- FL
20	1		*REAR FENDER INNER FRAME MEMBER	Not Necessary	580.60 FL	*- FL
21	1		*REAR BUMPER BODYKIT (ORI JAPAN)	Broken	3,500.00 FS	*1,600.00 FS
22	1		*REAR RIM L/H	Cut	800.00 FS	*680.00 FS
23	1		*REAR STICKER 70KM/H	Necessary	25.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,340.70	6,631.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,253.93	1,085.25
Total Parts (\$\$)	17,086.77	5,545.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ON ELECTRICAL WIRING	New	150.00	20.00
2	TO REMOVE ,REFIX REAR UNDERCARRIAGE	New	450.00	0.00
3	TO REMOVE ,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	250.00	0.00
4	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
5	TO RESPRAY UNDERCOATING	New	350.00	60.00
6	TO PANEL BEAT ,CUT ,WELD REMOVE & REPLACE PARTS	New	1,800.00	1,000.00
7	TO RESPRAY PAINT ON ACCIDENT AFFECTED PARTS	New	2,000.00	800.00
Gross Labour Cost (\$\$)			5,150.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >