

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22002792/UPA3Q2**Date:** 17/01/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : SLG9277E **Insured Vehicle No :** SMY5777Z
 Date of Loss: 20/03/2022 Nature of Claim: TP Claim No: MFL2022D0001551

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG9277E**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) Engine No: 1ZRY336747
 Reg. Date: 19/10/2016 (Man. Year: 2016) Chassis No: MR053REH104559394
 Colour: Grey Odometer: 137379 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,807.15	9,094.19	8,712.96	48.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,790.00	2,200.00	1,590.00	41.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,597.15	11,294.19	10,302.96	47.71
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	21,597.15	9,000.00	12,597.15	58.33
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
(S\$)		9,420.00		
Liable Amount (50.00%) (S\$)		4,710.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,717.45		
Global Sum Settlement (S\$)		4,700.00		

INSPECTION

Date of Assignment: 25/03/2022
 Date Inspected: 25/03/2022 Inspected At: T K LEE AUTOMOTIVE PTE LTD
 Estimated Period of Repair: 6.0 days 1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG9277E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	1,248.10 FL	*1,248.10 FL
2	1		*FRONT BONNET LOCK	Bent	135.50 FL	*135.50 FL
3	1		*FRONT BONNET LOCK CABLE	Not Necessary	89.90 FL	*- FL
4	1		*FRONT BONNET SEAL	Not Necessary	86.90 FL	*- FL
5	1		*FRONT BONNET INSULATOR	Not Necessary	221.43 FL	*- FL
6	8		*FRONT BONNET INSULATOR CLIPS	Not Necessary	44.00 FL	*- FL
7	1		*FRONT BONNET HINGES -RH/LH	O/S Twisted	230.40 FL	*115.20 FL
8	1		*FRONT BONNET STAND	Not Necessary	89.60 FL	*- FL
9	1		*FRONT BONNET STAND CLIP	Not Necessary	18.20 FL	*- FL
10	1		*FRONT BUMPER	Distorted	652.20 FL	*558.10 FL
11	1		*FRONT BUMPER LOWER GRILLE	Torn	181.92 FL	*181.92 FL
12	1		*FRONT BUMPER FOG LAMPS -RH/LH	N/S Not Necessary /O/S Cracked	742.50 FL	*371.25 FL
13	1		*FRONT BUMPER FOG LAMPS COVER -RH/LH	N/S Not Necessary /O/S Twisted	363.80 FL	*181.90 FL
14	1		*FRONT BUMPER SPONGE	Torn	140.63 FL	*140.63 FL
15	1		*FRONT BUMPER REINFORCEMENT	Bent	477.73 FL	*399.10 FL
16	2		*FRONT BUMPER SIDE RETAINER -RH/LH	Bent / Cracked	97.70 FL	*97.70 FL
17	1		*FRONT BUMPER UNDERCOVER	Torn	241.60 FL	*241.60 FL
18	1		*FRONT FENDER -RH/LH	N/S Repair / O/S Bent	1,716.20 FL	*858.10 FL
19	1		*FRONT FENDER INNER SHIELD -RH/LH	N/S Not Necessary / O/S Torn	462.70 FL	*231.35 FL
20	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	165.00 FL	*50.00 FL
21	1		*FRONT FENDER WHEEL HOUSING -RH	Repair	481.90 FL	*- FL
22	1		*FRONT GRILLE ASSY	Broken	643.10 FL	*643.10 FL
23	1		*FRONT GRILLE LOGO	Missing	86.60 FL	*86.60 FL
24	1		*FRONT GRILLE SEAL	Torn	42.20 FL	*42.20 FL
25	5		*FRONT GRILLE CLIPS	Necessary	27.50 FL	*27.50 FL
26	2		*FRONT HEADLAMPS -RH/LH	N/S Holder Cracked / O/S Broken	4,974.20 FL	*4,974.20 FL
27	4		*FRONT HEADLAMP LOWER BRACKETS -RH/LH	Not Necessary	192.80 FL	*- FL
28	2		*FRONT HEADLAMP SIDE GARNISHES -RH/LH	Not Necessary	131.00 FL	*- FL
29	1		*FRONT SUPPORT PANEL	Bent / Twisted	1,218.10 FL	*1,207.00 FL
30	1		*FRONT SUPPORT ABSORBER -RH	Not Necessary	481.60 FL	*- FL
31	1		*FRONT LOWER ARM -RH	Not Necessary	605.20 FL	*- FL
32	1		*FRONT KNUCKLE ARM	Not Necessary	459.50 FL	*- FL
33	1		*FRONT WHEEL BEARING	Not Necessary	191.60 FL	*- FL
34	1		*AIR CON CONDENSER	Not Necessary	1,487.43 FL	*- FL
35	1		*RADIATOR ASSY	Not Necessary	1,895.50 FL	*- FL
36	1		*RADIATOR TOP GARNISH	Twisted	181.20 FL	*181.20 FL
37	1		*RADIATOR FAN COWLING	Not Necessary	241.35 FL	*- FL
38	1		*RADIATOR SPARE TANK	Not Necessary	110.25 FL	*- FL
39	1		*HORN	Not Necessary	89.95 FL	*- FL
40	1		*ENGINE MOULDING -RH	Not Necessary	286.90 FL	*- FL
41	1		*ENGINE MOULDING -LH	Not Necessary	261.50 FL	*- FL
42	1		*WIPE TANK	Not Necessary	172.30 FL	*- FL

Report was unsubmitted during this print-out.

1/17/23, 11:19 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*WIPE TANK MOTOR	Not Necessary	110.25 FL	*- FL
44	1		*WIPE PANEL GARNISH	Not Necessary	591.60 FL	*- FL
45	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
46	1		*SET FRONT NUMBER PLATE WITH HOLDER	Distorted	65.00 FS	*40.00 FS
47	1		*FRONT SPORT WHEEL -RH	Not Necessary	550.00 FS	*- FS
48	1		*FRONT TYRE -RH	Not Necessary	250.00 FS	*- FS
49	1		*BOT AIR CON COIL	Necessary	60.00 FS	*30.00 FS
50	1		*BOT RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)						23,399.54 12,087.25
- List Item Discount on L Items 25.00/25.00% (\$\$)						5,592.39 2,993.06
Total Parts (\$\$)						17,807.15 9,094.19
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE ,REPLACE FRONT UNDERCARRIAGE	New	250.00	0.00
3	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	120.00	0.00
4	TO REMOVE & REPLACE AIR CON CONDENSER & RADIATOR & TOP UP GAS	New	150.00	100.00
5	TO TUFF KOTE	New	120.00	80.00
6	TO REMOVE ,REFIX ENGINE PARTS	New	200.00	0.00
7	TO PUTTY ,SRPAY PAINT & POLISH AFFECTED PARTS	New	1,400.00	1,100.00
8	TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACE DAMAGED PARTS	New	1,500.00	900.00
Gross Labour Cost (S\$)			3,790.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >