

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22002794/AQCE2**Date:** 04/10/2022**REFERENCE**

Insured/Claimant: RAMESH THIYAGARAJAN Policy No: 1900139775-02
Date of Loss: 23/03/2022 Nature of Claim: OD Claim No: 2883688110SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV2711K**
Make & Model: AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A) Engine No: CHZC30753
Reg. Date: 26/07/2019 (Man. Year: 2019) Chassis No: WAUZZZ8V4KA089311
Colour: Black Odometer: 42681 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$102,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,554.00	9,024.24	10,529.76	53.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,302.00	2,542.00	6,760.00	72.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,856.00	11,566.24	17,289.76	59.92
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	28,556.00	11,266.24	17,289.76	60.55
+ GST 7.00/7.00% (S\$)	1,998.92	788.64	1,210.28	60.55
Nett Amount (S\$)	30,554.92	12,054.88	18,500.04	60.55

INSPECTION

Date of Assignment: 28/03/2022
Date Inspected: 25/03/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,432.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	179.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	571.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-RH	Not Necessary	318.00 FS	*- FS
6	1		*FRONT BUMPER TRIM COVER-RH	Not Necessary	182.00 FS	*- FS
7	1		*FRONT BUMPER ADAPTER-RH	Not Necessary	42.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	1,578.00 FS	*1,262.40 FS
9	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	210.00 FS	*168.00 FS
10	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
11	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
12	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	210.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	211.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	847.00 FS	*- FS
15	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	136.00 FS	*- FS
16	1		*BONNET	Dented	3,348.00 FS	*2,678.40 FS
17	1		*BONNET ATTACHMENT PARTS	Not Necessary	172.00 FS	*- FS
18	2		*BONNET HINGE-LH/RH	Bent	136.00 FS	*108.48 FS
19	1		*BONNET CATCH HOOK	Not Necessary	100.00 FS	*- FS
20	1		*BONNET STRIKER-RH	Not Necessary	123.00 FS	*- FS
21	1		*BONNET EDGE PROTECTION	Deformed	31.00 FS	*24.72 FS
22	1		*BONNET LOCK MICRO-SWITCH	Not Necessary	228.00 FS	*- FS
23	1		*BONNET BOWDEN CABLE-CENTER	Not Necessary	64.00 FS	*- FS
24	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
25	1		*BONNET SOUND ABSORBER	Not Necessary	244.00 FS	*- FS
26	1		*BONNET CATCH HOOK LOWER	Not Necessary	71.00 FS	*- FS
27	1		*HEADLIGHT-RH	Cut	5,879.00 FS	*4,703.20 FS
28	1		*LIFT CYLINDER-RH	Not Necessary	156.00 FS	*- FS
29	1		*LIFT CYLINDER HOSE	Not Necessary	78.00 FS	*- FS
30	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
31	1		*RADIATOR AIR GUIDE-RH	Not Necessary	28.00 FS	*- FS
32	1		*RADIATOR SEAL-RH OUTER	Not Necessary	9.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE-LH	Not Necessary	28.00 FS	*- FS
34	1		*RADIATOR AIR GUIDE-UPPER CENTER	Not Necessary	14.00 FS	*- FS
35	1		*LOCK CARRIER	Not Necessary	806.00 FS	*- FS
36	6		*RADIATOR COOLANT	Not Necessary	282.00 FS	*- FS
37	1		*INTAKE AIR GUIDE	Not Necessary	59.00 FS	*- FS
38	1		*INTAKE AIR GUIDE COVER	Not Necessary	30.00 FS	*- FS
39	1		*INTAKE AIR GUIDE OUTER	Not Necessary	21.00 FS	*- FS
40	1		*INTAKE AIR GUIDE HOSE	Not Necessary	69.00 FS	*- FS
41	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
42	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **19,554.00** **9,024.24**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER,ADDITIONAL RADIATORE AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT PRESSURISE,VACUUM AND REGAS	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND RHS HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,000.00	1,000.00
5	TO RESPRAY FRONT BUMPER,BONNET HINGES AND RHS UPPER A-PILLAR	New	3,000.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (S\$)	2,542.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >