

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4749L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	GUARD, RR BUMPER, LOWER (DISC 25%)	SCRATCHED	558.30	418.72
1	COVER, GUARD RR BUMPER LOWER (DISC 25%)	MISSING	14.80	11.10
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
2	PAD, RR BUMPER, RH & LH, 1	NOT NECESSARY	3.80	-
2	PAD, RR BUMPER, RH & LH, 2	NOT NECESSARY	3.80	-
2	PAD, RR BUMPER, RH & LH, 3	NOT NECESSARY	3.80	-
1	PAD, RR BUMPER, CTR	NOT NECESSARY	2.20	-
2	SEAL, RR BUMPER ARM, RH & LH	NOT NECESSARY	11.00	-
2	STOPPER, RR BUMPER, RH & LH	NOT NECESSARY	4.30	-
1	RETAINER, RR BUMPER, RH	NOT NECESSARY	112.70	-
1	RETAINER, RR BUMPER, LH	NOT NECESSARY	111.50	-
1	CLIPS PIECE, FRT & RR BUMPER	NOT NECESSARY	1.50	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	ANTENNA, ELECTRICAL KEY	NOT NECESSARY	60.30	-
1	END PANEL SUB-ASSY, BODY LOWER BACK	NOT NECESSARY	629.80	-
1	COVER, RR BUMPER ASSY	TO REPAIR SEE LABOUR	423.90	-
			2,440.50	429.82
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF COVER, RR BUMPER ASSY.		676.00	200.00
	SPRAY PAINT.		558.00	200.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
			1,614.00	400.00
	GRAND TOTAL		4,054.50	829.82

Report Ref No. NS/INC22002798/Rvce2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		650.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC22002798/Rvce2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

(KLAUGRICHE

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**