

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1566Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
3	SENSOR - RR PARK DIST CONT (DISC 10%)	NOT NECESSARY	175.50	-
1	FASCIA-RR BPR (DISC 10%)	NOT NECESSARY	682.62	-
1	FASCIA-RR BPR LWR (DISC 10%)	NOT NECESSARY	207.61	-
1	FINISHER-RR BPR - RH (DISC 10%)	NOT NECESSARY	42.68	-
1	BRACKET ASM-RR BPR (DISC 10%)	NOT NECESSARY	26.86	-
1	BRACKET-RR BPR FASCIA LWR MTG (DISC 10%)	NOT NECESSARY	11.51	-
1	BAR ASM- RR BPR IMP (DISC 10%)	NOT NECESSARY	305.78	-
1	LINER ASM-RR W/H PNL - R (DISC 10%)	NOT NECESSARY	76.94	-
1	WINDOW ASM-OTR, RH (DISC 10%)	NOT NECESSARY	226.33	-
1	SEALANT SIKAFLEX (DISC 10%)	NOT NECESSARY	37.00	-
1	PANEL - BODY SH OTR-R (DISC 10%)	TO REPAIR SEE LABOUR	1,291.40	-
			3,084.23	-
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF PANEL - BODY SH OTR-R.	NOT NECESSARY	1,800.00	-
	SPRAY PAINT.		856.00	200.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	120.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO CHECK & RESET SYSTEM FUNCTION.	NOT NECESSARY	350.00	-
	ISOLATED OF (EVI).	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT REAR QUARTER GLASS RH.	NOT NECESSARY	120.00	-
			3,696.00	200.00
	GRAND TOTAL		6,780.23	200.00





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		200.00
(CONFIRMED)		

Report Ref No. NS/INC22002800/Rqcs2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

T

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser