

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002805/UEA3Q2**Date:** 06/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700067969
Claimant Vehicle No :	SND5439Z	Insured Vehicle No :	SLF3334T
Date of Loss:	25/03/2022	Nature of Claim:	TP
		Claim No:	6889289001SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND5439Z	Engine No:	2AZ4A52702
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Chassis No:	ACR507134890
Reg. Date:	23/01/2017 (Man. Year: 2016)	Odometer:	91835 km
Colour:	White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	PROXES 8 mm	Rear Left Side:	PROXES 8 mm
Front Right Side:	PROXES 8 mm	Rear Right Side:	PROXES 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,124.92	1,492.42	2,632.50	63.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,410.00	550.00	28.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,084.92	2,902.42	3,182.50	52.30
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	6,084.92	2,300.00	3,784.92	62.20
+ GST 7.00/7.00% (S\$)	425.94	161.00	264.94	62.20
Nett Amount (S\$)	6,510.86	2,461.00	4,049.86	62.20
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
(S\$)		2,761.00		
Liabe Amount (50.00%) (S\$)		1,380.50		
Global Sum Settlement (S\$)		1,380.00		

INSPECTION

Date of Assignment:	04/04/2022		Jin Auto Services Pte Ltd (Defu)
Date Inspected:	04/04/2022	Inspected At:	Blk 14 Defu Lane 10, #01-410/412
Estimated Period of Repair:	3.0 days		Singapore 539195

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR PROTECTOR	Repair	1,250.00 FL	*- FL
2	1		*FRONT RH DOOR PROTECTOR CHROME MLD	Not Necessary	115.00 FL	*- FL
3	1		*REAR RH DOOR (NPA)	Repair	0.00 FL	*- FL
4	1		*REAR RH DOOR PROTECTOR	Deformed / Warped	1,350.00 FL	*1,250.00 FL
5	1		*REAR RH DOOR PROTECTOR CHROME MLD	Scratched	135.00 FL	*135.00 FL
6	1		*REAR RH FENDER (NPA)	Repair	0.00 FL	*- FL
7	1		*REAR RH FENDER PROTECTOR	Repair	235.00 FL	*- FL
8	1		*REAR BUMPER	Deformed	604.90 FL	*604.90 FL
9	1		*REAR RH RIM	Repair	1,810.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$)					5,499.90	1,989.90
- List Item Discount on L Items 25.00/25.00% (\$)					1,374.98	497.48
Total Parts (\$)					4,124.92	1,492.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING (PEARL WHITE)	New	1,100.00	1,050.00
2	LABOUR CHARGE	New	480.00	300.00
3	WIRING (TRANSFER DOOR MECHANISM)	New	180.00	0.00
4	CHECK ALIGNMENT	New	80.00	60.00
5	TUFF KOTE	New	120.00	0.00
Gross Labour Cost (\$)			1,960.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >