

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002813/RVY3M4**Date:** 31/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00050142201

Claimant Vehicle No : GY9500A**Insured Vehicle No :** SMV1067G

Date of Loss: 21/03/2022

Nature of Claim: TP

Claim No: SNM22D201956/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GY9500A**

Make & Model: TOYOTA HIACE, 2.0 (M)

Reg. Date: 25/10/2018 (Man. Year: 2018)

Colour: White

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

Engine No: 1KD2827794

Chassis No: JTFHT02P700245552

Odometer: 114616 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Front Left Side: OHTSU 6 mm

Front Right Side: OHTSU 6 mm

The above values represent the remaining tyre treads depth

Rear Tyre Size: 195R15

Rear Left Side: OHTSU 6 mm

Rear Right Side: OHTSU 6 mm

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,356.20	6,173.50	182.70	2.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,738.00	7,078.00	2,660.00	27.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	16,094.20	13,251.50	2,842.70	17.66
+ GST 7.00/7.00% (\$\$)	1,126.59	927.61	198.98	17.66
Nett Amount (\$\$)	17,220.79	14,179.11	3,041.68	17.66

INSPECTION

Date of Assignment: 27/03/2022

Date Inspected: 08/04/2022

Estimated Period of Repair: 9.0 days

Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 May 2022)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GY9500A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SEALANT (NETT)	Necessary	100.00 FS	*100.00 FS
2	1		*REAR BUMPER COVER	Deformed	481.80 FS	*481.80 FS
3	3		*REAR BUMPER BRACKET	Not Necessary	83.10 FS	*- FS
4	1		*L/R SIDE BPR RETAINER	Not Necessary	24.80 FS	*- FS
5	1		*R/R SIDE BPR RETAINER	Not Necessary	24.80 FS	*- FS
6	1		*REAR OUTER FLR MEMBER	Bent	363.70 FS	*363.70 FS
7	1		*REAR INNER FLR MEMBER	Bent	1,172.50 FS	*1,172.50 FS
8	1		*REAR BACK DOOR PANEL	Bent	2,293.20 FS	*2,293.20 FS
9	1		*GLASS SUB-ASSY, BACK	Necessary	1,419.80 FS	*1,419.80 FS
10	1		*EMBLEM, SYMBOL	Necessary	72.20 FS	*72.20 FS
11	1		*TOYOTA HIACE EMBLEM	Necessary	51.60 FS	*51.60 FS
12	1		*PLATE, BACK DOOR	Bent	112.30 FS	*112.30 FS
13	1		*2 PT SENSOR FOR HIACE	Not Working	56.40 FS	*56.40 FS
14	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	6,356.20	6,173.50
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RESET AND REPROGRAMME ECU.	New	180.00	180.00
2	CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.	New	180.00	180.00
3	DRILL HOLE TO INSTALL REVERSE SENSOR.	New	180.00	180.00
4	REMOVE TAIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR.	New	328.00	328.00
5	REPLACE REAR WINDSCREEN GLASS TO ASSIST REPAIR.	New	450.00	450.00
6	REMOVE BOOT INTERIOR UPHOLSTERY TO ASSIST REPAIR.	New	720.00	360.00
7	INSTALL TAIL-GATE COMPANY LOGO.	New	400.00	0.00
8	SUPPLY AND INSTALL 70KM.H AND 5PAX STICKER.	New	30.00	30.00
9	SUPPLY AND INSTALL 70KM/H AND 5PAX STICKER.	New	0.00	-
10	REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN TAIL-GATE, TAIL-LAMP PANEL, REAR BUMPER, FLOOR PANEL AND AFFECTED PORTION OF CAR.	New	4,320.00	3,600.00
11	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	New	2,950.00	1,770.00
Gross Labour Cost (\$\$)			9,738.00	7,078.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >