

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002814/KVY3N2**Date:** 19/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00004192100
Claimant Vehicle No :	GBB6198P	Insured Vehicle No :	SLC4665Y
Date of Loss:	22/03/2022	Nature of Claim:	TP
		Claim No:	SNM22D202021/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB6198P	Engine No:	1KD1943339
Make & Model:	TOYOTA DYNA 100 MANUAL, 3.0 D (M)	Chassis No:	JTFAT35Y90K200849
Reg. Date:	22/09/2009 (Man. Year: 2009)	Odometer:	422583 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	155R12X8(D)
Front Left Side:	Othsu 8 mm	Rear Left Side:	Falken 9/9 mm
Front Right Side:	Othsu 8 mm	Rear Right Side:	Falken 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,742.40	1,522.69	219.71	12.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	970.00	460.00	32.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,172.40	2,492.69	679.71	21.43
Approved Total (Overridden) (\$\$)		2,000.00		
Nett Amount (\$\$)	3,172.40	2,000.00	1,172.40	36.96

INSPECTION

Date of Assignment:	30/03/2022	
Date Inspected:	29/03/2022 Inspected At:	LH Express Motor Trading (HQ) BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO IND. PARK 2 Singapore 569541
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Apr 2022)	
Parts:	N/A	TOYOTA DYNA 100 MANUAL 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB6198P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S CORNER PANEL	Bent	305.20 FL	*264.30 FL
2	1		*FRONT O/S HEADLAMP ASSY	Cracked	550.60 FL	*550.60 FL
3	1		*FRONT GRILLE	Mtg Cracked	485.70 FL	*438.85 FL
4	1		*FRONT GRILLE EMBLEM	Necessary	55.70 FL	*55.70 FL
5	1		*FRONT BUMPER	Bent	465.70 FL	*465.70 FL
6	1		*FRONT O/S BUMPER BRACKET	Repair	205.20 FL	*- FL
7	1		*FRONT O/S STEP GARNISH	Cut	255.10 FL	*255.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,323.20	2,030.25
- List Item Discount on L Items 25.00/25.00% (\$\$)	580.80	507.56
Total Parts (\$\$)	1,742.40	1,522.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	700.00	400.00
2	TO PUTTY AND SPRAY PAINT	New	700.00	550.00
3	CHECK & RECONNECT WIRING	New	30.00	20.00
Gross Labour Cost (\$)			1,430.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >