

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG22002816/EVY3E2

Date: 12/05/2022

REFERENCE

| | | | | |
|-------------------|---------------------------|------------------|------------|------------------------|
| Insured/Claimant: | LIM JOO LENG (LIN YULONG) | Policy No: | 2070106565 | |
| Date of Loss: | 25/03/2022 | Nature of Claim: | OD | Claim No: 3922425920SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---------------------------------|-------------|-------------------|
| Reg No: | SGH8719H | | |
| Make & Model: | MITSUBISHI ATTRAGE, 1.2 CVT (A) | Engine No: | 3A92UHM3517 |
| Reg. Date: | 16/07/2020 (Man. Year: 2018) | Chassis No: | MMBSTA13AKH000719 |
| Colour: | Red | Odometer: | 21737 km |
| Engine Capacity: | 1193 cc | | |
| Market Value/New Car Price: | S\$70,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 185/55 R15 | Rear Tyre Size: | 185/55 R15 |
| Front Left Side: | Yokohama 4 mm | Rear Left Side: | Yokohama 4 mm |
| Front Right Side: | Yokohama 4 mm | Rear Right Side: | Yokohama 4 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts | 2,614.69 | 2,563.13 | 51.56 | 1.97 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,305.00 | 2,835.00 | 1,470.00 | 34.15 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 6,919.69 | 5,398.13 | 1,521.56 | 21.99 |
| + GST 7.00/7.00% (S\$) | 484.38 | 377.87 | 106.51 | 21.99 |
| Nett Amount (S\$) | 7,404.07 | 5,776.00 | 1,628.07 | 21.99 |

INSPECTION

Date of Assignment: 28/03/2022

Date Inspected: 28/03/2022 Inspected At:

Estimated Period of Repair: 6.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1 | 1 | | *SUNDRIES | Necessary | 50.00 FS | *20.00 FS |
| 2 | 1 | | *UNPAINTED BODYKITS | Broken | 1,643.00 FS | *1,643.00 FS |
| 3 | 1 | | *LAMP ASSY, COMB, RR LH | Broken | 337.00 FL | *337.00 FL |
| 4 | 1 | | *BRACKET, RR BUMPER, LH | Not Necessary | 28.00 FL | *- FL |
| 5 | 1 | | *FACE, RR BUMPER | Dented | 751.00 FL | *751.00 FL |
| 6 | 1 | | *MUD GUARD, RR LH (Supplementary) | Broken | 41.00 FL | *41.00 FL |
| 7 | 1 | | *CLIPS (x10) (Supplementary) | Necessary | 40.00 FL | *40.00 FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|----------|----------|
| Sub Total (\$\$) | 2,890.00 | 2,832.00 |
| - List Item Discount on L Items 23.00/23.00% (\$\$) | 275.31 | 268.87 |
| Total Parts (\$\$) | 2,614.69 | 2,563.13 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | REPLACE REAR BUMPER, BODY KIT & AFFECTED AREA. REPAIR ON REAR LH FENDER | New | 1,800.00 | 450.00 |
| 2 | PAINT WORK ON REAR BUMPER, BODY KIT & REAR LH FENDER | New | 1,050.00 | 1,050.00 |
| 3 | REMOVE & REPLACE BODY KIT | New | 120.00 | 80.00 |
| 4 | REMOVE & INSTALL REAR PARKING ASSISTS FOR FACILITATE REPAIR | New | 120.00 | 80.00 |
| 5 | PERFORM RUST PREVENTION | New | 40.00 | 0.00 |
| 6 | CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | New | 30.00 | 30.00 |
| 7 | TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM | New | 120.00 | 120.00 |
| 8 | REPAIR REAR END PANEL & LH REAR FENDER (Supplementary) | New | 675.00 | 675.00 |
| 9 | RESPRAY ON REAR END PANEL & LH REAR FENDER (Supplementary) | New | 350.00 | 350.00 |
| Gross Labour Cost (\$) | | | 4,305.00 | 2,835.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >